



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4613H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	TO REPAIR SEE LABOUR	2,000.00	-
12	FRONT BUMPER CLIP (WCP)	NOT NECESSARY	60.00	-
1	FRONT BUMPER SIDE RETAINER UPPER RH (WCP)	DISTORTED	95.00	95.00
1	FRONT BUMPER SIDE RETAINER LOWER RH (WCP)	SERVICEABLE	95.00	-
1	FRONT BUMPER LOWER GARNISH RH (WCP)	SERVICEABLE	155.00	-
1	FRONT BUMPER UNDERCOVER (WCP)	SERVICEABLE	430.00	-
1	FRONT FENDER RH (WCP)	BENT	710.00	710.00
1	FRONT FENDER COWLING RH (WCP)	SERVICEABLE	350.00	-
8	FRONT FENDER COWLING CLIPS (WCP)	NOT NECESSARY	40.00	-
1	HEADLAMP RH (WCP)	MTG CRACKED	750.00	750.00
1	PARKING SENSOR OUTER RH (WCP)	SERVICEABLE	135.00	-
4	PARKING SENSOR RING (WCP)	NOT NECESSARY	40.00	-
1	FRONT WHEEL HUB RH WITH BEARING (WCP)	SERVICEABLE	275.00	-
	COST PLUS 10%		513.50	155.50
			5,648.50	1,710.50
<u>SPECIAL NETT ITEMS</u>				
1	SPORT RIM RHF - CHECK PRICE (NPA) (SN)	SERVICEABLE	-	-
1	TYRE RHF - CHECK PRICE (NPA) (SN)	SERVICEABLE	-	-
			-	-
<u>LABOUR</u>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR BONNET, FRONT WHEELHOUSE PANEL RH & INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		600.00	300.00

Report Ref No. CS/SMO23002992/Kcy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT WHEELHOUSE PANEL RH.		800.00	400.00
			1,580.00	720.00
GRAND TOTAL			7,228.50	2,430.50
RECOMMENDED COST OF REPAIRS				2,430.50

Report Ref No. CS/SMO23002992/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.