SHENG LI LAI

2 Kaki Bukit Avenue 2 #01-36 Kaki Bukit Autohub Singapore 417921

Tel: 68420302 Fax: 67460295

Name : Lin XiaoRong

Address : C/o: 2 Kaki Bukit Avenue 2

#01-36 Kaki Bukit Autohub

Singapore 417921

Final repair cost of SLT 7369 T

Date of accident :

Vehicle Model :

28 March 2022

Toyota C-HR

Lump Sum Repair Costs

\$ 9,200.00

Singapore Dollars: Nine Thousand And Two Hundred Only.



24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

INVOICE

Invoice No.:

CL/220175

Lin XiaoRong

C/o: Sheng Li Lai

Ref No.:

SLL/03/2206/TP

2 Kaki Bukit Avenue 2

#01-36 Kaki Bukit Autohub, Singapore 417921

Date:

7 April 2022

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

SURVEY INSPECTION FOR VEHICLE NO.

SLT 7369 T

- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 650.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CLAPPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

24 Penshurst Place, Singapore 556440 Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Lin XiaoRong

Date

7 April 2022

C/o: Sheng Li Lai

Our ref

: SLL/03/2206/TP

2 Kaki Bukit Avenue 2

#01-36 Kaki Bukit Autohub, Singapore 417921

Accident Date

: 28 March 2022

Type of Survey : Third Party

Inspection Date Repairer Name

30 March 2022

: Sheng Li Lai

2 Kaki Bukit Avenue 2

#01-36 Kaki Bukit Autohub, Singapore 417921

PARTICULARS OF VEHICLE

Registration No : SLT 7369 T

Year / Capacity 🙏

2017 / 1797 cc

Make / Model

: Toyota C-HR

Colour

Grey

Chassis No

: ZYX102080088

Mileage

147614

Engine No

: 2ZR8208384

CONDITION OF TYRES

		Make	Size	Thread Balance	Rim
Front Nearside	*	Michelin	225/50 R18	5 mm	Sport
Front Offside		Michelin	225/50 R18	5 mm	Sport
Rear Nearside	*	Michelin	225/50 R18	5 mm	Sport
Rear Offside	\$	Michelin	225/50 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion. (Details refer to the photographs attached)

Enclosed number of photographs:

94

copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$9,200.00 on a contractual basis.

Under normal circumstances, the repair period would be about 8 (Eight) working days.



Our Ref No.:

SLL/03/2206/TP

Otro	Description	Conditions	Repairer's	Revised
Qty	Description	Conditions	Estimate	Amount
	SPARE PARTS - LIST ITEMS			
1	Rear windscreen inner seal	Necessary	\$ 180.54	\$ 180.54
1	Rear tailgate	Damage	\$ 1,020.30	\$ 1,020.30
1	Rear tailgate outer garnish	Damage	\$ 882.20	\$ 882.20
1	Rear tailgate inner board	Damage	\$ 233.95	\$ 233.95
2	Rear tailgate lamps	Damage	\$ 1,000.22	\$ 1,000.22
1	Rear tailgate lock	Damage	\$ 448.30	\$ 448.30
1	Rear tailgate rubber	Necessary	\$ 200.33	\$ 200.33
1	Rear tailgate "C-HR" emblem	Necessary	\$ 100.33	\$ 100.33
1	Rear tailgate "HYBRID" emblem	Necessary	\$ 90.97	\$ 90.97
1	Rear tailgate inner pull pocket	Damage	\$ 80.54	\$ 80.54
2	Rear taillamps	O/S Damage	\$ 1,201.50	\$ 600.75
1	Rear end panel	Damage	\$ 625.90	\$ 625.90
1	Rear end panel inner garnish	Damage	\$ 244.50	\$ 244.50
1	Rear keyless sensor	Damage	\$ 266.40	\$ 266.40
1	Rear bumper	Damage	\$ 700.33	\$ 700.33
2	Rear bumper brackets	Damage	\$ 200.64	\$ 200.64
1	Rear bumper centre grille cover	Damage	\$ 188.30	\$ 188.30
1	Rear bumper lower garnish	Damage	\$ 357.70	\$ 357.70
2	Rear bumper reflector garnishes	Damage	\$ 114.60	\$ 114.60
1	Rear bumper reinforcement	Damage	\$ 318.91	\$ 318.91
2	Rear bumper side retainers	Necessary	\$ 119.20	\$ 119.20
4	Rear bumper PDC sensors	Damage	\$ 801.28	\$ 801.28
1	Rear bumper tow hook cover	Damage	\$ 90.97	\$ 90.97
1	Rear floor panel	Damage	\$ 625.00	\$ 625.00
1	Rear exhaust silencer	Damage	\$ 1,200.32	\$ 1,200.32
2	Rear exhaust mountings	Necessary	\$ 200.64	\$ 200.64
1	Rear exhaust heat shield	Damage	\$ 165.77	\$ 165.77
1	Rear o/s fender	Intact	\$ 803.30	
			\$ 12,462.94	\$ 11,058.89
		Less 25%	\$ 3,115.74	\$ 2,764.72
Total Cost - List Items			\$ 9,347.21	\$ 8,294.17



Our Ref No.:

SLL/03/2206/TP

Qty	Description	Conditions	Repairer's Estimate	Rev	ised Amount
.117	List Items Total c/f		\$ 9,347.21	\$	8,294.17
	SPECIAL NETT ITEMS				
1	Rear windscreen sealant	Necessary	\$ 80.00	\$	50.00
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$	50.00
1	Rear floor panel insulator	Necessary	\$ 150.00	\$	150.00
	Total Cost - Special Nett items		\$ 280.00	\$	250.00

Total cost of parts

\$ 9,627.21 \$ 8,544.17



Our Ref No.:

SLL/03/2206/TP

S/No	Description		Repairer's	Revised	
2/1/0			Estimate		Amount
	Total cost of parts c/f	\$	9,627.21	\$	8,544.17
	<u>LABOUR</u>				
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$	80.00	\$	50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$	120.00	\$	80.00
3	To remove and refit rear reverse sensor.	\$	150.00	\$	120.00
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$	80.00	\$	80.00
5	To remove and refit rear windscreen glass.	\$	180.00	\$	120.00
6	To remove, refit and replace exhaust silencer and mountings.	\$	120.00	\$	80.00
7	To apply undercoating on repaired and replaced panel.	\$	180.00	\$	120.00
8	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,600.00	\$	1,250.00
9	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,500.00	\$	1,100.00
	GRAND TOTAL	\$	13,637.21	\$	11,544.17



Our Ref No.:

SLL/03/2206/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 9,200.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser



























































































































































