

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS3/MSG22013005/SWY3M4-1  
**Date:** 26/05/2023

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001927715
<b>Claimant Vehicle No :</b>	EY64A	<b>Insured Vehicle No :</b>	SDG1600C
Date of Loss:	14/12/2022	Nature of Claim:	TP
		Claim No:	294970

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>EY64A</b>	Engine No:	27492030198459
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Chassis No:	WDD2120362B049831
Reg. Date:	03/09/2014 (Man. Year: 2014)	Odometer:	156413 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	21,088.06	4,129.93	16,958.13	80.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	1,870.00	1,970.00	51.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,928.06</b>	<b>5,999.93</b>	<b>18,928.13</b>	<b>75.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	24,928.06	4,800.00	20,128.06	80.74
<b>+ GST 8.00/8.00% (S\$)</b>	1,994.24	384.00	1,610.24	80.74
<b>Nett Amount (S\$)</b>	<b>26,922.30</b>	<b>5,184.00</b>	<b>21,738.30</b>	<b>80.74</b>

**INSPECTION**

Date of Assignment:	30/12/2022		
Date Inspected:	03/01/2023	Inspected At:	ETALIA AUTOWORKZ PTE LTD 53 UBI AVENUE 1 #01-16 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934
Estimated Period of Repair:	4.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2023)
Parts:	143	MERCEDES-BENZ E250 2.0 SEDAN (R18) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EY64A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP	Not Necessary	3,424.32 FL	*- FL
2	1		*FRT BUMPER	Repair	1,550.85 FL	*- FL
3	1		*RHF FENDER	Repair	1,123.11 FL	*- FL
4	1		*RHF FENDER LOWER CHROME MOULDING	Necessary	59.06 FL	*59.06 FL
5	1		*RHF ALLOY RIM	Scratched	809.05 FL	*650.00 FL
6	1		*RHF WHEEL HUB ASSY	Not Necessary	803.76 FL	*- FL
7	1		*RHF SHOCK ABSORBER	Not Necessary	1,374.80 FL	*- FL
8	1		*RHF KNUCKLE ARM	Not Necessary	980.61 FL	*- FL
9	1		*RHF CONTROL ARM	Not Necessary	662.84 FL	*- FL
10	1		*RHF LOWER ARM	Not Necessary	596.87 FL	*- FL
11	1		*RHF LOWER ARM BALL JOINT	Not Necessary	152.37 FL	*- FL
12	1		*RH PILLAR CHROME TRIM STRIP	Scratched	537.18 FL	*100.00 FL
13	1		*RH SIDE MIRROR OUTER COVER	Scratched	407.53 FL	*160.00 FL
14	1		*RH SIDE MIRROR OUTER LOWER	Cracked	199.04 FL	*120.00 FL
15	1		*RH SIDE MIRROR FRAME	Scratched	1,080.11 FL	*890.00 FL
16	1		*RHF DOOR	Dented	2,805.27 FL	*2,300.00 FL
17	1		*RHF DOOR GLASS OUTER CHROME	Not Necessary	166.18 FL	*- FL
18	1		*RHF DOOR OUTER HANDLE	Not Necessary	384.27 FL	*- FL
19	1		*RHF DOOR CHROME MOULDING	Dented	156.76 FL	*156.76 FL
20	1		*RHR DOOR	Repair	2,780.14 FL	*- FL
21	1		*RHR DOOR GLASS OUTER CHROME	Not Necessary	191.63 FL	*- FL
22	1		*RHR DOOR CHROME MOULDING	Necessary	152.99 FL	*152.99 FL
23	1		*RR BUMPER	Repair	1,462.38 FL	*- FL
24	1		*BONNET	Not Necessary	0.00 FL	*- FL
			(NPA)			
25	1		*RHF WINDSCREEN PILLAR	Not Necessary	0.00 FL	*- FL
			(NPA)			
26	1		*RHF FENDER	Repeated	0.00 FL	*- FL
			(NPA)			
27	1		*RHR FENDER	Repeated	0.00 FL	*- FL
			(NPA)			
28	1		*RR BUMPER	Repeated	0.00 FL	*- FL
			(NPA)			
29	1		*RHF TYRE (DEPRECIATE 30%)	Not Necessary	300.00 FS	*- FS
30	1		*BOT BRAKE FLUID	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,181.12	4,588.81
- List Item Discount on L Items 5.00/10.00% (\$\$)	1,093.06	458.88
Total Parts (\$\$)	21,088.06	4,129.93

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP	New	70.00	30.00
2	TO REMOVE, CHECK AND REPLACE RHF UNDERCARRIAGE PARTS. (INCLUDE FLUSH AND BLEED BRAKES SYSTEM)	New	250.00	80.00
3	TO CONDUCT WHEEL ALIGNMENT (2X)	New	120.00	120.00
4	TO TRANSFER RHF DOOR COMPONENT PARTS TO NEW DOOR	New	120.00	40.00
5	TO TRANSFER RHR DOOR COMPONENT PARTS TO NEW DOOR	New	120.00	0.00
6	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,500.00	600.00
7	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,600.00	1,000.00
8	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,840.00</b>	<b>1,870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >