PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0040123 Date of Report : 22/02/2023

To: Ms Soh Qi Hui, Cindy Date of Assignment : 03/01/2023

C/o. 51 Ubi Ave 1 #01-04
Paya Ubi Industrial Park
Singaporc 408933
Report requested by : Ms Soh Qi Hui, Cindy
Date of Accident : 14/12/2022
Date of Inspection : 03/01/2023

Claim No. : Third Party Claim

Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : EY64A Engine Capacity (cc) : 1991
Make & Model : M/Benz E250 Mileage (km) : 156413km

 Date of Registration
 : 03/09/2014
 Chassis / Frame No.
 : WDD2120362B049831

 Colour
 : Met. Black
 Engine No.
 : 27492030198459

TYRE CONDITION

Front LH : 5 mm Front RH : 5 mm Make : Falken Make : Falken

Rear LH : 5 mm Rear RH : 5 mm Make : Falken Make : Falken

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location: M/s. Etalia Autoworkz Pte. Ltd.

51, Ubi Ave 1, #01-04, Paya Ubi Industrial Park, Singapore 408933

ASSESSMENT

Repairer's Estimate : \$ 24,928.06 Revised Amount : \$ 16,195.58

Less Excess : \$

Recommended Reserve : \$ 12,960.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Report No.: PAS/TP/0040123

Vehicle No: EY64A

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Etalia Autoworkz Pte. Ltd., 51, Ubi Ave 1, #01-04, Paya Ubi Industrial Park, Singapore 408933.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHS portion. (The RHF roadwheel was also affected)

DAMAGES

The front bumper, RHF fender, RHF alloy rim, RHF wheel hub assy, RHF knuckle arm, RHF lower arm, RHF control arm, bonnet, RHF windscreen pillar, RH side mirror assy, RHF door, RHR door, RHR fender, rear bumper, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$16,195.58.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$12,960.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



Vehicle No: EY64A

Report No.: PAS/TP/0040123

APPRAISEMENT SCHEDULE

		Parts Descriptions	Condition		Re	pairer's	Our	
S/No.	Qty				Estimate (S\$)		Assessment (S\$)	
					•	2 404 20	C.	
1	1 pc	RH headlamp	Refit		\$	3,424.32	\$	1 550 05
2	1 pc	Frt bumper	Dented/Deform		\$	1,550.85	\$	1,550.85
3	1 pc	RHF fender	Dented/Repair		\$	1,123.11	\$	50.06
4	1 pc	RHF fender lower chrome moulding			\$	59.06	\$	59.06
5	1 pc	RHF alloy rim	Dented/Deface		\$	809.05	\$	809.05
6	1 pc	RHF wheel hub assy	Warped/Dama	iged	\$	803.76	\$	803.76
7	1 pc	RHF shock absorber	Refit		\$	1,374.80	\$	
8	1 pc	RHF knuckle arm	Bent/Distorted	1	\$	980.61	\$	980.61
9	1 pc	RHF control arm	Bent		\$	662.84	\$	662.84
10	1 pc	RHF lower arm	Bent		\$	596.87	\$	596.87
11	1 pc	RHF lower arm ball joint	Bent		\$	152.37	\$	152.37
12	I pc	RH pillar chrome trim strip	Dented/Deface	ed	\$	537.18	\$	537.18
13	1 pc	RH side mirror outer cover	Cracked		\$	407.53	\$	407.53
14	1 pc	RH side mirror outer lower	Cracked		\$	199.04	\$	199.04
15	1 pc	RH side mirror frame	Cracked/Dama	aged	\$	1,080.11	\$	1,080.11
16	l pc	RHF door	Dented/Distor		\$	2,805.27	\$	2,805.27
17	1 pc	RHF door glass outer chrome	Dented/Deface		\$	166.18	\$	166.18
18	1 pc	RHF door outer handle	Grazed/Repair	r	\$	384.27	\$	-
19	l pc	RHF door chrome moulding	Dented/Neces		\$	156.76	\$	156.76
20	1 pc	RHR door	Dented/Distor		\$	2,780.14	\$	2,780.14
21	l pc	RHR door glass outer chrome	Refit		\$	191.63	\$	-
22	1 pc	RHR door chrome moulding	Necessary		\$	152.99	\$	152.99
23	l pc	Rr bumper	Grazed/Repair	•	\$	1,462.38	\$	-
		Bonnet	Grazed/Repair		•	-,	(Refer lal	oour no. 7)
24	1 pc	RHF windscreen pillar	Grazed/Repair			(Rc	5.5	no. 6 & 7)
25 26	l pc	RHF fender	Dented/Repair					no. 6 & 7)
	1 pc	RHR fender	Dented/Repair					no. 6 & 7)
27	1 pc		Grazed/Repair			(Refer labour no. 6 & 7)		
28	1 pc	Rr bumper	Grazed/Repair	L				
					\$	21,861.12		13,900.61
				Less Discount: 5%	\$	1,093.06	5%_\$	695.03
				List Parts Sub-Total:	\$	20,768.06	\$	13,205.58
1	1 pc	RHF tyre (Depreciate 30%)	Cut	S/N	\$	300.00	\$	210.00
2		Brake fluid	Necessary	S/N	\$	20.00	\$	20.00
			9	Special Nett Sub-Total :	\$	320.00	\$	230.00
							The same of the sa	
				Parts Total:	\$	21,088.06	\$	13,435.58