

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003016/AYA3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700044189
Claimant Vehicle No :	SJK5078S	Insured Vehicle No :	SJQ1698Y
Date of Loss:	28/02/2023	Nature of Claim:	TP
		Claim No:	9456928425SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK5078S	Engine No:	3SZ2157147
Make & Model:	TOYOTA RUSH, 1.5 X (A)	Chassis No:	J200E0022943
Reg. Date:	23/10/2008 (Man. Year: 2008)	Odometer:	127094 km
Colour:	Black		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,400.52	4,411.25	2,989.27	40.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,860.00	1,870.00	50.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,130.52	6,271.25	4,859.27	43.66
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	11,130.52	5,000.00	6,130.52	55.08
+ GST 8.00/8.00% (S\$)	890.44	400.00	490.44	55.08
Nett Amount (S\$)	12,020.96	5,400.00	6,620.96	55.08
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,762.00		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment:	02/03/2023	SM Automotive (HQ)
Date Inspected:	02/03/2023 Inspected At:	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43
Estimated Period of Repair:	5.0 days	SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,540.80 FL	*1,404.00 FL
2	1		*REAR TAILGATE LOCK	Not Necessary	415.95 FL	*- FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	793.25 FL	*463.00 FL
4	1		*REAR WEATHERSTRIPE	Not Necessary	154.50 FL	*- FL
5	1		*REAR TAILGATE EMBLEM RUSH	Necessary	56.40 FL	*56.40 FL
6	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	194.60 FL	*194.60 FL
7	1		*REAR TAILGATE SPARE TYRE BRACKET	Not Necessary	289.50 FL	*- FL
8	1		*REAR TAILGATE SPARE TYRE OUTER COVER	Cracked	1,589.50 FL	*1,485.00 FL
9	1		*REAR TAILGATE SPARE TYRE INNER COVER	Cracked	654.20 FL	*435.00 FL
10	1		*REAR BUMPER	Deformed	855.70 FL	*855.70 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	171.80 FL	*171.80 FL
12	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	159.20 FL	*- FL
13	2		*REAR BUMPER REFLECTOR	Not Necessary	191.80 FL	*- FL
14	1		*REAR END PANEL INNER	Repair	321.50 FL	*- FL
15	1		*REAR END PANEL OUTER	Repair	381.60 FL	*- FL
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	281.80 FL	*- FL
17	2		*REAR END PANEL AIR VENT	Not Necessary	49.60 FL	*- FL
18	1		*REAR TAILLAMP	O/S Cracked	779.00 FL	*389.50 FL
19	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
20	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	150.00 FS	*60.00 FS
21	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
23	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
24	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,620.70	5,775.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,220.18	1,363.75
Total Parts (\$\$)	7,400.52	4,411.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,500.00	700.00
2	LABOUR FOR SPRAY PAINTING	New	1,200.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & REFIX REAR UPHOLSTERY /ROOF LINING	New	200.00	40.00
5	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	40.00
6	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
7	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	200.00	80.00
8	LABOUR FOR REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			3,730.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >