



Century Motors (Singapore) Pte Ltd

6 Marsiling Lane

Singapore 739145

E: claims@autoinsure.com.sg

T: (65) 3157 2626

GST No.: 192800002R

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLN1760S (CK)

Your ref: SMR1396C

Date:

21-Mar-23

BY EMAIL ONLY

(claims@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

LIBERTY INSURANCE PTE LTD

51 CLUB STREET #03-00 LIBERTY HOUSE SINGAPORE : 069428

Assessed Vehicle No

: SLN1760S

Car Make and Model

: HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Date of Accident

: 20-Mar-23

Date of Assessment

: 21-Mar-23

We have carried out a physical assessment of SLN1760S at our workshop Auto Insure Pte Ltd sustained damages to the FRONT & REAR portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT & REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

L/

Adjusted Amount

\$ 17,187.38

Est. Repair Days

.

Pursuant to your instruction, we have <u>NOT AUTHORIZED</u> repair.

The assessment was conducted on a <u>"WITHOUT PREJUDICE"</u> basis.


If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

Century Motors (Singapore) Pte Ltd For any reliance on this report by any third party.



Our Ref: SLN1760S Your Ref: SMR1396C

s/NO	QTY DESCRIPTIONS ASSESSED CONDITION		CONDITION	EST. BY WORKSHOP		
		PARTS REPLACEMENT - LIST ITEMS				
1	1	TAILGATE LAMP LH X M7		\$ 94	8.90	
2	1	TAILGATE LAMP RH X 17		\$ 94	3.90	
3	1	TAIL LAMP RH X 29		\$ 850	0.90	
4	1	TAIL LAMP LH X 122			0.90	
5	1	REAR BUMPER de		\$ 73	.90	
6	1	REAR BUMPER CORNER LHXA		T. C.	.90	
7	1 "	REAR BUMPER CORNER RH PEPEL		\$ 265	.90	
8	1	REAR BUMPER REFLECTOR LH XAA		58.00	.50	
9	1 .	REAR BUMPER REFLECTOR RH		\$ 89	.50	
10	1	REAR BUMPER INNER BRACKET LH			.80	
11	1	REAR BUMPER INNER BRACKET RH 7 KAN			.80	
12	1	REAR BUMPER SIDE RETAINER RH 📈		1 2	.90	
13	1	REAR BUMPER SIDE RETAINER LH			.90	
14	1	REAR END PANEL		73898	:50	
15	1	REAR END PANEL INNER TRIM de			90	
16	1	TAILGATE ST		\$ 1,980	80	
17	1	TAILGATE HINGE LH X M			80	
18	1	TAILGATE HINGE RH X AA		199	80	
19	1	TAILGATE WEATHERSTRIP		\$ 185.	1000000	
20	1	TAILGATE LOCK SW/		\$ 135.		
21	1	TAILGATE LOCK STRIKER		\$ 45.		
22	1	TAILGATE LOGO A		\$ 85.		
23	1	TAILGATE EMBLEM(VEZEL)		\$ 55.	1	
24	1	TAILGATE EMBLEM(HYBRID)		\$ 55.		
25	1	TAILGATE GARNISH X 7A		\$ 325.		
26	1	TAILGATE INNER TRIM : X11		\$ 145.5		
27	1	TOOLS BOX ? Xan		\$ 320.	1	
28	1	SPARE WHEEL COVER		\$ 455.		
29	1	FRONT BUMPER de-		\$ 1,265.		
30	1	FRONT BUMPER TOWING COVER 64		\$ 454	1 .	
31	1	FRONT BUMPER REINFORCEMENT 7.XM		\$ 665.9	200	
32	1	COONT BUILDED CVIDT		\$ 398.5	1	
33	1	FRONT BUMPER LOWER GRILLE 7. LAN		\$ 165.9		
34	1	FRONT GRILLE COVER X NA		\$ 375.9		
35	1	FRONT GRILLE CM		\$ 855.9		
36	1	FRONT GRILLE LOGO ALL			0 2	
37	1	FRONT SUPPORT PANEL X MA		\$ 825.9		
38	1	REAR WINDSCREEN MOULDING		\$ 240.9	1	
			SUB TOTAL	\$ 15,155.3	5	
			LESS 20%		-	
			TOTAL AMOUNT	\$ 12,124.24	1	

Our Ref: SLN1760S Your Ref: SMR1396C

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	WINDSCREEN SEALANT		\$ 50.00
2	1	REVERSE SENSORS L & R		\$ 259.00
3	1	REAR BUMPER CLIPS		\$ 50.00
4	1	FRONT NUMBER PLATE WITH HOLDER C		\$ 35.00
5	1	REAR NUMBER PLATE WITH HOLDER X	11	\$ 35.00
			SUB TOTAL	\$ 430.00
		•	TOTAL PARTS COST	\$ 12,554.24

Our Ref: SLN1760S Your Ref: SMR1396C

	T. BY WORKSHOP	EST. B	DESCRIPTION		
1.			WORK		
9000	1 50000		INGS TO COMMENCE REPAIRS;		
100	1,600.00	\$	AREAS AND REPLACED THE	1	
80	100.00	\$	CIDENT AND CHECK FOR PROPER	2	
8009	1,200.00	\$	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED		
60	100.00	\$	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		
60	190.00	\$	TO REMOVE & REFIT TAILGATE MECHANISM		
)	100.00	\$	TO REMOVE & REFIT WINDSCREEN		
120	50.00	\$	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		
XXX	50.00	\$	TO VACUUM, WAXING & CLEAN		
170	60.00	\$	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS		
	15,914.24	\$	TOTAL BEFORE GST	9	
	1,273.14	\$	GST 8%		
	17,187.38	\$	TOTAL (PARTS & LABOUR):		

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 17,187.38 for lump sum with the third party insurance.

Yours Faithfully,

Ck Loh

Claims Estimator

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No itlegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Passe 4 fter report





Century Motors (Singapore) Pte Ltd 6 Marsiling Lane Singapore 739145

E: claims@autoinsure.com.s T: (65) 3157 262

GST No.: 192800002

Page No.

SUPPLEMENTARY ITEMS

Our Ref: SLN1760S

Your Ref: SMR1396X

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP \$1,053.88	
1	1	CONDENSER &			
2	1	TEMPERATURE SENSOR CM			\$250.38
			SUB TOTAL	\$	1,304.2
			LESS 20%	\$	260.85
			TOTAL AMOUNT	\$	1,043.4