

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123003027/SVP3E2**Date:** 07/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00173912200
Claimant Vehicle No :	SMR7210R	Insured Vehicle No :	SGK1109Z
Date of Loss:	22/03/2023	Nature of Claim: TP	Claim No: SNM23D202166/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7210R	Engine No:	CZD885154
Make & Model:	AUDI Q3, 1.4 TFSI S TRONIC (17") (A)	Chassis No:	WAUZZZF35L1023725
Reg. Date:	20/01/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45Z R19	Rear Tyre Size:	255/45Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,303.00	16,559.60	22,743.40	57.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,070.00	1,060.00	7,010.00	86.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,373.00	17,619.60	29,753.40	62.81
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	47,373.00	14,000.00	33,373.00	70.45
+ GST 8.00/8.00% (S\$)	3,789.84	1,120.00	2,669.84	70.45
Nett Amount (S\$)	51,162.84	15,120.00	36,042.84	70.45

INSPECTION

Date of Assignment:	23/03/2023	
Date Inspected:	24/03/2023	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	M1-SUV	AUDI Q3 1.4 TFSI S TRONIC (17") (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR7210R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,890.00 FL	*1,390.00 FL
2	1		*REAR BUMPER LOWER	Cracked	540.00 FL	*540.00 FL
3	1		*REAR BUMPER GUIDE SECTION RH	Cracked	112.00 FL	*112.00 FL
4	1		*REAR BUMPER GUIDE SECTION LH	Cracked	112.00 FL	*112.00 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	48.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR RH	Cracked	49.00 FL	*49.00 FL
7	1		*REAR BUMPER REFLECTOR LH	Cracked	49.00 FL	*49.00 FL
8	1		*REAR BUMPER PARKING AID SENSOR (4PCS)	Faulty (2Pcs Only)	976.00 FL	*488.00 FL
9	4		*REAR BUMPER PARKING AID SEAL RING	Not Necessary	6.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	736.00 FL	*- FL
11	1		*REAR FENDER WHEEL ARCH GARNISH RH	Not Necessary	302.00 FL	*- FL
12	1		*REAR FENDER WHEEL ARCH GARNISH LH	Not Necessary	302.00 FL	*- FL
13	1		*REAR TAILGATE	Not Necessary	3,985.00 FL	*- FL
14	1		*REAR TAILGATE EMBLEM	Not Necessary	138.00 FL	*- FL
15	1		*REAR TAILGATE Q3 EMBLEM	Not Necessary	99.00 FL	*- FL
16	1		*REAR TAILGATE LOCK	Not Necessary	310.00 FL	*- FL
17	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	78.00 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	298.00 FL	*- FL
19	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	573.00 FL	*- FL
20	1		*REAR TAILGATE TAILLAMP ASSEMBLY RH	Not Necessary	1,091.00 FL	*- FL
21	1		*REAR TAILGATE TAILLAMP ASSEMBLY LH	Not Necessary	1,091.00 FL	*- FL
22	1		*REAR TAILLAMP ASSEMBLY RH	Not Necessary	1,091.00 FL	*- FL
23	1		*REAR TAILLAMP ASSEMBLY LH	Not Necessary	1,091.00 FL	*- FL
24	1		*REAR END PANEL UPPER	Dented	348.00 FL	*348.00 FL
25	1		*REAR END PANEL LOWER	Not Necessary	768.00 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	225.00 FL	*- FL
27	1		*REAR FENDER WHEEL ARCH GARNISH RH	Not Necessary	283.00 FL	*- FL
28	1		*REAR FENDER WHEEL ARCH GARNISH LH	Not Necessary	283.00 FL	*- FL
29	1		*REAR SILENCER	Not Necessary	1,271.00 FL	*- FL
30	1		*DUAL CLIP	Not Necessary	96.00 FL	*- FL
31	2		*RETAINING RING - CENTRE / RH	Not Necessary	40.00 FL	*- FL
32	1		*RETAINING RING BRACKET LH	Not Necessary	87.00 FL	*- FL
33	1		*EXHAUST TAILPIPE CHROME TIP	Not Necessary	268.00 FL	*- FL
34	1		*FRONT BUMPER	Cracked	1,285.00 FL	*987.00 FL
35	1		*FRONT BUMPER CLOSING ELEMENT RH	Not Necessary	66.00 FL	*- FL
36	1		*FRONT BUMPER CLOSING ELEMENT LH	Not Necessary	66.00 FL	*- FL
37	1		*FRONT BUMPER GRILLE CENTRE	Not Necessary	242.00 FL	*- FL
38	1		*FRONT BUMPER GRILLE RH	Not Necessary	124.00 FL	*- FL
39	1		*FRONT BUMPER GRILLE LH	Not Necessary	124.00 FL	*- FL
40	1		*FRONT BUMPER CLOSING ELEMENT LOWER	Not Necessary	212.00 FL	*- FL
41	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	426.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Not Necessary	171.00 FL	*- FL
43	1		*FRONT BUMPER AIR GUIDE GRILLE LH	Not Necessary	171.00 FL	*- FL
44	1		*RADIATOR GRILLE	Cracked	1,594.00 FL	*1,275.00 FL
45	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	271.00 FL	*- FL
46	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	114.00 FL	*114.00 FL
47	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	974.00 FL	*- FL
48	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	43.00 FL	*- FL
49	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	43.00 FL	*- FL
50	1		*FRONT BUMPER TOP COVER	Not Necessary	137.00 FL	*- FL
51	1		*CAUTION STICKER	Not Necessary	16.00 FL	*- FL
52	1		*AIR COND STICKER	Not Necessary	9.00 FL	*- FL
53	4		*FRONT PARKING SENSOR	Not Necessary	976.00 FL	*- FL
54	4		*FRONT PARKING SENSOR SEAL RING	Not Necessary	6.00 FL	*- FL
55	1		*FRONT HEADLAMP ASSEMBLY RH	Cracked	5,952.00 FL	*5,952.00 FL
56	1		*FRONT HEADLAMP ASSEMBLY LH	Cracked	5,952.00 FL	*5,952.00 FL
57	1		*FRONT HEADLAMP MOUNTING RH	Not Necessary	132.00 FL	*- FL
58	1		*FRONT HEADLAMP MOUNTING LH	Not Necessary	132.00 FL	*- FL
59	1		*LIFT CYLINDER RH	Not Necessary	231.00 FL	*- FL
60	1		*LIFT CYLINDER LH	Not Necessary	231.00 FL	*- FL
61	1		*LIFT CYLINDER HOSE RH	Not Necessary	92.00 FL	*- FL
62	1		*LIFT CYLINDER HOSE LH	Not Necessary	92.00 FL	*- FL
63	1		*RADIATOR AIR GUIDE RH	Not Necessary	43.00 FL	*- FL
64	1		*RADIATOR AIR GUIDE LH	Not Necessary	43.00 FL	*- FL
65	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	48.00 FL	*- FL
66	1		*FRONT FENDER WHEEL ARCH GARNISH RH	Not Necessary	283.00 FL	*- FL
67	1		*FRONT FENDER WHEEL ARCH GARNISH LH	Not Necessary	283.00 FL	*- FL
68	1		*FRONT FENDER INNER COWLING RH	Not Necessary	260.00 FL	*- FL
69	1		*FRONT FENDER INNER COWLING LH	Not Necessary	260.00 FL	*- FL
70	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
71	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
72	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*SET REAR BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS
74	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
75	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
76	1		*SET REAR FENDER WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
77	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
78	1		*SET RADIATOR GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
79	1		*SET FRONT FENDER WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
80	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
81	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
82	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
83	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
84	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	41,290.00	17,428.00
- List Item Discount on L Items 5.00/5.00% (\$)	1,987.00	868.40
Total Parts (\$)	39,303.00	16,559.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS (FRONT)	New	1,200.00	200.00
2	TO PANEL BEAT, REMOVE & REFIX PARTS (REAR)	New	1,800.00	400.00
3	TO SPRAY PAINT AFFECTED AREAS (FRONT)	New	1,200.00	200.00
4	TO SPRAY PAINT AFFECTED AREAS (REAR)	New	1,800.00	200.00
5	WIRING & BULB CHECK (FRONT) }	New	100.00	30.00
6	WIRING & BULB CHECK (REAR) }	New	100.00	0.00
7	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	0.00
8	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	0.00
9	TO RMEOVE & REFIX REAR TAILGATE REVERSE CAMERA	New	150.00	0.00
10	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	0.00
11	TO REMOVE & REFIX FRONT BUMPER SENSOR	New	120.00	30.00
12	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
13	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	0.00
14	TO REMOVE & REFIX FRONT HEADLAMP CONTROL UNIT & POWER MODULE	New	200.00	0.00
15	TO APPLY ANTI RUST ON AFFECTED PARTS	New	100.00	0.00
16	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
17	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (\$\$)			8,070.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >