

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CC 4/HSB 23003028/Up 3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

)

1377

Vehicle: IN / OUT

2745/19845

27/6/13

have video of folder

6/4/23 2/5 @ 3100 in demand Alin.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
23/3/23
2/s \$ 3100/
3 days

VEHICLE No: SKQ 6257S

1PC	REAR BUMPER	DD/Re	1525.21	\$1,691.00
1PC	REAR BUMPER BEAM	sub	565.00	\$603.00
1PC	REAR BUMPER LOWER DIFFUSER	two/scent	420.00	\$645.00
1PC	REAR BUMPER INNER RETAINER	one	166.00	\$215.00
2PCS	REAR BUMPER SIDE HOLDERS @\$85.00	11		\$170.00 X
2PCS	REAR BUMPER REFLECTORS @\$95.00	11		\$190.00 X
2PCS	REAR BUMPER PDC SENSORS @\$165.00	not repair		\$330.00 12C
1PC	REAR END PANEL OUTER	12		\$545.21 X
1PC	REAR END PANEL INNER	12		\$488.00 X
				\$4,877.21

5%

S.NETT

1SET	REAR BUMPER CLIPS	11	\$50.00
1PC	REAR END PANEL SEALANT	11	\$50.00 X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO SPRAY RUST PROOFING	\$80.00	X
TO RESET & REPROGRAMME SYSTEM	\$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	450
TO PUTTY & SPRAY PAINTING	\$1,080.00	500
TOTAL	\$7,307.21	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2911.21
52
2765.64
50
1080
3885.64
20%
3116.