

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23003029/HNY3E2**Date:** 14/04/2023REFERENCEInsured/Claimant: TAN YONG PHIO MRS WONG YONG PHIO
Date of Loss: 28/01/2023Policy No: SP2003215160-01
Nature of Claim: OD

Claim No: 202332004976

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL3721B**
 Make & Model: BMW 216D, 1.5 D ACTIVE TOURER LED EU6 (A) Engine No: 38045042B37C15A
 Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: WBA2B32080V926096
 Colour: Blue Odometer: 93639 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: S\$81,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,881.70	4,410.90	470.80	9.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	610.00	610.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,491.70	5,020.90	470.80	8.57
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	5,491.70	4,000.00	1,491.70	27.16
+ GST 0.00/8.00% (S\$)	0.00	320.00	-320.00	
Nett Amount (S\$)	5,491.70	4,320.00	1,171.70	21.34

INSPECTION

Date of Assignment: 23/03/2023 Present Location:

Chew Goon Motor (AMK)

Chew Goon Motor (AMK)

Date Inspected: 23/03/2023 Inspected At:

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17,
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: Edward**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2023)
Parts: M1-MPV	BMW 216D 1.5 D ACTIVE TOURER LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3721B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Bumper (WCP)	Cut	950.00 F	*854.00 F
2	12		*Front Bumper Clips (WCP)	Necessary	18.00 F	*18.00 F
3	1		*Front Bumper Emblem (WCP)	Necessary	62.00 F	*50.00 F
4	1		*Front Bumper Center Air Grille (WCP)	Cut	130.00 F	*130.00 F
5	1		*Front Bumper Sensor (WCP)	Cracked	120.00 F	*120.00 F
6	1		*Front Bumper Number Plate Base Holder (WCP)	Dented	62.00 F	*62.00 F
7	1		*Front Bumper Sponge (WCP)	Cracked	95.00 F	*95.00 F
8	1		*Front Bumper Reinforcement (WCP)	Buckled	420.00 F	*420.00 F
9	1		*Front Bumper Beam (WCP)	Not Necessary	130.00 F	*- F
10	1		*Front Bumper Fog Lamp LH (WCP)	Not Necessary	190.00 F	*- F
11	1		*Front Bumper Fog Lamp Cover LH (WCP)	Cracked	80.00 F	*80.00 F
12	1		*Front Bumper Inner Air Duct (Plastic) (WCP)	Cut	170.00 F	*170.00 F
13	2		*Grilles (WCP)	Cut	170.00 F	*170.00 F
14	1		*Headlamp LH (WCP)	Cut	1,800.00 F	*1,800.00 F
15	1		*Front Number Plate	Dented	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,442.00	4,014.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	439.70	396.90
Total Parts (\$\$)	4,881.70	4,410.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Conduct Electrical Check, Focus Headlamp	New	30.00	30.00
2	Labour Charge - Panel Beating, Repairing Headlamp Panel,Support & Part Replacement	New	380.00	380.00
3	To Respray Affected Areas	New	200.00	200.00
			Gross Labour Cost (\$\$)	610.00
				610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >