

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | |
|------------------------------------|---|---|---------------------|-------------------------|--|
| | HSBC LIFE (SINGA | APORE) PTE LTD | Ref: | CS3/HSB23003031/Snp3e2 | |
| | 10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018 | AY FINANCIAL CENTRE TOWER | Date: | 19/06/2023 | |
| | ATTN: KHOR SAW | THENG | Code: | HSB | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | SHB 4109P | Veh. Inspected | SNE 4922X | |
| | Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 | |
| | Claim No. | S3M04KBR | Excess (\$) | 0.00 | |
| | Assign From | KHOR SAW THENG | Assign Date | 23/03/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA VEZEL | c.c | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | 2017 | |
| | Chassis No. | RU31219188 | Colour | GREY | |
| | Odometer | 211341 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| | General | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | 5 mm | |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | 5 mm | |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUS UNDERCARRIAGE | SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND AGE. | | | |
| 5. General Information | | | | | |
| | Accident Date | 09/03/2023 | Inspect Date / Time | 23/03/2023 (03:00 PM) | |
| | Survey held at | GARAGE 13 PTE LTD | | | |
| | 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 | | | | |
| 5a. | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000 | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORM | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | |
| | Depart Def No. CC2/HCD22002024/Cnn2c2 | | | | |

Report Ref No. CS3/HSB23003031/Snp3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

DEOD Anta Ornantiant OAE Linear LAmunian

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$