



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 3424M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/H HEADLAMP ASSY (HID)	BROKEN	658.20	658.20
1	HEADLAMP LOWER BEAM	NOT NECESSARY	78.20	-
1	FRONT R/H FENDER	DENTED / BENT	725.88	450.80
1	FRONT BUMPER	TORN	652.74	622.40
1	FRONT BUMPER SIDE RETAINER	BENT	35.77	35.77
	LESS 20% DISCOUNT		-430.16	-353.43
			1,720.63	1,413.74
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIP (SN)	NECESSARY	40.00	30.00
			40.00	30.00
	<u>LABOUR</u>			
	TO KNOCK INNER BRACKETS AND PANEL.TO REPLACE AND ALIGN ABOVE ITEMS TO SYMMETRICAL SPEC.		750.00	320.00
	TO SPRAY PAINT FRONT BUMPER AND FENDER.		800.00	600.00
	TO CARRY OUT WIRE CHECKING AND ADJUST HEADLAMP.		80.00	20.00
			1,630.00	940.00
	GRAND TOTAL		3,390.63	2,383.74
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/SMO23003036/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.