



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23003038/Any3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 27/04/2023

ATTN: MARCUS XIAO

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 4485A	Veh. Inspected	GBG 4435S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1215128-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	23/03/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFAT35Y70K208531	Colour	SILVER
Odometer	121150 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75R15	YOKOHAMA	6 mm
L/H Front Tyre	195/75R15	YOKOHAMA	6 mm
R/H Rear Tyre	155R12C	YOKOHAMA	6 mm
L/H Rear Tyre	155R12C	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/03/2023	Inspect Date / Time	23/03/2023 (03:00 PM)
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**