4/13/23, 10:58 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3

CS3/III23003039/WVY3E2

Date: 13/04/2023

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:

Claimant Vehicle No: SJR2629K Insured Vehicle No: SLK3765G

Date of Loss: 19/03/2023 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR2629K

 Make & Model:
 MERCEDES-BENZ C180K, 1.6 (A)
 Engine No:
 27191031344410

 Reg. Date:
 25/04/2011 (Man. Year: 2011)
 Chassis No:
 WDD2040452A525756

Colour: Yellow Odometer: 164394 km

Engine Capacity: 1597 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm
Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date Inspected:

Date of Assignment: 23/03/2023

Chip Soon Auto Supply Co Pte Ltd (HQ)

BLOCK 9002 #01-74 TAMPINES STREET 93.

TAMPINES INDUSTRIAL PARK A

Singapore 528836

Estimated Period of Repair: 0.0 days

Adjuster: Mohdakid Manager: VERON CHEN

27/03/2023 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/13/23, 10:58 AM Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 13 Apr 2023) Part Source: MRM-SG

Parts: 143 MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJR2629K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

4/13/23, 10:58 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >