

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23003042/AWY3E2**Date:** 14/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SFH3743G**Insured Vehicle No :** SMT3560X

Date of Loss: 23/03/2023

Nature of Claim:

TP

Claim No: CDMPG23000701

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFH3743G**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4841514

Reg. Date: 18/02/2009 (Man. Year: 2008)

Chassis No: MR053ZEE106132421

Colour: Black

Odometer: 185687 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,861.30	3,585.02	2,276.28	38.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,920.00	960.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,741.30	5,505.02	3,236.28	37.02
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	8,741.30	4,400.00	4,341.30	49.66
+ GST 8.00/8.00% (S\$)	699.30	352.00	347.30	49.66
Nett Amount (S\$)	9,440.60	4,752.00	4,688.60	49.66

INSPECTION

Date of Assignment: 23/03/2023

Date Inspected: 24/03/2023 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB

Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFH3743G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	949.10 FL	*840.00 FL
2	1		*REAR BOOTLID 1.6 EMBLEM	Necessary	40.10 FL	*40.10 FL
3	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	53.20 FL	*53.20 FL
4	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	53.20 FL	*53.20 FL
5	1		*REAR BOOTLID LOGO EMBLEM	Necessary	66.90 FL	*66.90 FL
6	2		*REAR BOOTLID HINGES L/R	Not Necessary	148.80 FL	*- FL
7	2		*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	36.00 FL	*- FL
8	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	20.90 FL	*- FL
9	1		*REAR BOOTLID MECHANISM LOCK	Damaged	121.10 FL	*121.10 FL
10	1		*REAR BOOTLID OUTER HANDLE	Not Necessary	291.50 FL	*- FL
11	2		*REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R	Not Necessary	70.00 FL	*- FL
12	2		*REAR BOOTLID REFLECTOR INNER COVER L/R	Not Necessary	210.00 FL	*- FL
13	2		*REAR BOOTLID REFLECTOR L/R	Not Necessary	610.80 FL	*- FL
14	1		*REAR BOOT LID WEATHER STRIP	Cut	209.90 FL	*209.90 FL
15	1		*REAR BUMPER	Distorted	660.80 FL	*660.80 FL
16	1		*REAR BUMPER END SEAL COVER	Not Necessary	39.90 FL	*- FL
17	2		*REAR BUMPER REFLECTOR L/R	Cracked	93.80 FL	*93.80 FL
18	2		*REAR BUMPER SIDE BRACKET L/R	Damaged	75.20 FL	*75.20 FL
19	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	157.40 FL	*- FL
20	1		*REAR BUMPER SPONGE	Cracked	153.80 FL	*153.80 FL
21	1		*REAR END PANEL	Dented	727.70 FL	*727.70 FL
22	1		*REAR END PANEL INNER TOP GARNISH	Deformed	231.60 FL	*231.60 FL
23	2		*REAR END PANEL NOSE BRACKET L/R	Dented	186.00 FL	*186.00 FL
24	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	70.00 FL	*- FL
25	1		*REAR EXHAUST SILENCER BOX	Repair	569.30 FL	*- FL
26	2		*REAR TAILLAMP BLACK GASKET L/R	Necessary	59.60 FL	*59.60 FL
27	2		*REAR TAILLAMP INNER PANEL L/R	Repair	188.60 FL	*- FL
28	2		*REAR TAILLAMP L/R	Cracked	1,029.40 FL	*730.00 FL
29	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	143.80 FL	*143.80 FL
30	1		*SET REAR BOOTLID OUTER HANDLE CLIPS	Not Necessary	30.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
32	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
33	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	7,678.40 4,696.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,817.10 1,111.68
					Total Parts (\$\$)	5,861.30 3,585.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
5	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	60.00
6	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			2,880.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >