



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 5195Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	700.80	700.80
1	REAR BUMPER RETAINER	DEFORMED	76.40	76.40
1	REAR BUMPER REFLECTOR	NOT NECESSARY	72.00	-
1	END PANEL	NOT NECESSARY	328.00	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,578.40	-
2	REAR DOOR HINGE	LOWER SCRATCHED	172.00	86.00
1	REAR DOOR CHECKER RH	NOT NECESSARY	110.00	-
1	REAR DOOR LOCK RH	NOT NECESSARY	258.00	-
1	REAR DOOR RUBBER RH	NECESSARY	135.00	135.00
1	REAR DOOR FRAME WEATHERSTRIP	NOT NECESSARY	185.00	-
1	TAILLAMP RH	BROKEN	258.70	258.70
1	TAILLAMP PANEL RH	BENT	256.00	256.00
1	REAR FENDER RH	BUCKLED	986.80	986.80
1	SLIDING DOOR RAIL RH	NOT NECESSARY	225.00	-
1	REAR FENDER INNER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	SLIDING DOOR RH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-534.21	-249.97
			4,807.89	2,249.73
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR GLASS SEALANT (SN)	NOT NECESSARY	50.00	-
1	5 PAX (SN)	NECESSARY	10.00	10.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			280.00	10.00
<b><u>LABOUR</u></b>				
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR DOOR RH AND REAR FENDER INNER PANEL RH.		1,500.00	1,000.00
	TO RESPRAY AFFECTED PORTION.		1,500.00	800.00
	TO REMOVE AND REFIT REAR DOOR GLASS RH.	NOT NECESSARY	150.00	-

Report Ref No. CS/TP23003047/Rqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS RH.	NOT NECESSARY	150.00	-
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS		50.00	30.00
	RUST PROOFING.		100.00	60.00
			3,450.00	1,890.00
<b>GRAND TOTAL</b>			<b>8,537.89</b>	<b>4,149.73</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,300.00</b>

Report Ref No. CS/TP23003047/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.