

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003055/APA3Q2**Date:** 23/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210038583
Claimant Vehicle No :	SKU2089R	Insured Vehicle No :	SMZ2217M
Date of Loss:	02/03/2023	Nature of Claim:	TP
		Claim No:	7366200395SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2089R	Engine No:	2ARU227861
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004009310
Reg. Date:	06/07/2015 (Man. Year: 2015)	Odometer:	155893 km
Colour:	Blue		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,139.37	18,148.90	21,990.47	54.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,510.00	5,560.00	7,950.00	58.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,649.37	23,708.90	29,940.47	55.81
Approved Total (Overridden) (S\$)		16,600.00		
Nett Amount (S\$)	53,649.37	16,600.00	37,049.37	69.06
+ Loss of Use (20.0 x S\$100.00/day) (S\$)		2,000.00		
+ Doc/Search Fee (S\$)		26.75		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		18,686.75		
Global Sum Settlement (S\$)		18,680.00		

INSPECTION

Date of Assignment:	06/03/2023	
Date Inspected:	06/03/2023	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	18.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	596.80 FL	*596.80 FL
2	1		*FRONT BUMPER GRILLE LOGO	Necessary	80.10 FL	*80.10 FL
3	1		*FRONT BUMPER GRILLE (UPPER)	Cracked	799.50 FL	*586.00 FL
4	2		*FRONT BUMPER GRILLE (UPPER)TOP CHROME	Cracked	380.40 FL	*380.40 FL
5	1		*FRONT BUMPER GRILLE (LOWER)	Not Necessary	399.50 FL	*- FL
6	1		*FRONT BUMPER GRILLE (LOWER) TOP CHROME	Cracked	180.60 FL	*180.60 FL
7	1		*FRONT NUMBER PLATE HOLDER GARNISH	Deformed	80.70 FL	*80.70 FL
8	2		*FRONT BUMPER FOGLAMP	Cracked	496.60 FL	*496.60 FL
9	2		*FRONT BUMPER FOGLAMP RING (CHROME)	Not Necessary	166.40 FL	*- FL
10	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	58.70 FL	*- FL
11	2		*FRONT BUMPER SENSOR	Not Necessary	536.60 FL	*- FL
12	2		*FRONT BUMPER SENSOR RING	Necessary	57.20 FL	*57.20 FL
13	2		*FRONT BUMPER SIDE AIR VENT	Not Necessary	472.20 FL	*- FL
14	1		*FRONT BUMPER BOTTOM COVER GARNISH	Not Necessary	258.80 FL	*- FL
15	2		*FRONT BUMPER RETAINER	Necessary	190.60 FL	*190.60 FL
16	1		*FRONT BUMPER REINFORCEMENT	Dented	425.90 FL	*425.90 FL
17	1		*FRONT BUMPER SPONGE	Deformed	80.70 FL	*80.70 FL
18	2		*HEADLAMP	Cracked	3,615.00 FL	*3,615.00 FL
19	2		*HEADLAMP TOP CHROME	Not Necessary	170.20 FL	*- FL
20	1		*FRONT FENDER	N/S Buckled	1,731.80 FL	*798.00 FL
21	2		*FRONT FENDER TOP INNER GARNISH	Not Necessary	270.20 FL	*- FL
22	2		*FRONT FENDER INNER COWLING	Not Necessary	371.00 FL	*- FL
23	1		*FRONT FENDER EMBLEM VVTI	N/S Necessary	139.80 FL	*69.90 FL
24	1		*BONNET	Dented	1,477.90 FL	*1,267.00 FL
25	1		*BONNET MOULDING	Missing	209.80 FL	*209.80 FL
26	2		*BONNET DAMPER	Not Necessary	281.20 FL	*- FL
27	1		*BONNET INSULATOR	Not Necessary	525.10 FL	*- FL
28	2		*BONNET HINGE	Not Necessary	153.00 FL	*- FL
29	1		*BONNET RUBBER	Not Necessary	78.10 FL	*- FL
30	1		*BONNET LOCK	Not Necessary	213.70 FL	*- FL
31	2		*BONNET STOPPER	Not Necessary	40.20 FL	*- FL
32	1		*BRACE PANEL	Bent	135.20 FL	*135.20 FL
33	1		*RADIATOR SUPPORT PANEL	Buckled	1,368.60 FL	*845.00 FL
34	2		*HORN	Not Necessary	242.60 FL	*- FL
35	1		*AIRCON CONDENSOR	Dented	1,948.80 FL	*1,485.00 FL
36	1		*AIRCON FAN MOTOR	Not Necessary	448.30 FL	*- FL
37	1		*AIRCON FAN BLADE	Not Necessary	165.80 FL	*- FL
38	1		*AIRCON PIPE	Not Necessary	346.30 FL	*- FL
39	1		*AIR DUCT	Not Necessary	178.10 FL	*- FL
40	1		*RADIATOR	Not Necessary	2,128.30 FL	*- FL
41	1		*RADIATOR SPARE TANK	Not Necessary	97.70 FL	*- FL
42	1		*RADIATOR FAN COWLING	Not Necessary	468.30 FL	*- FL
43	1		*RADIATOR FAN MOTOR	Not Necessary	475.40 FL	*- FL
44	1		*RADIATOR FAN BLADE	Not Necessary	179.10 FL	*- FL
45	2		*RADIATOR SIDE GARNISH	Torn	311.20 FL	*96.00 FL
46	1		*REAR BUMPER	Distorted	657.60 FL	*657.60 FL
47	1		*REAR BUMPER DIFFUSER	Deformed	193.30 FL	*193.30 FL
48	2		*REAR BUMPER REFLECTOR	Not Necessary	144.60 FL	*- FL
49	2		*REAR BUMPER SIDE RETAINER (SIDE)	Necessary	208.80 FL	*208.80 FL
50	2		*REAR BUMPER SCREW COVER GARNISH	Not Necessary	56.20 FL	*- FL
51	1		*REAR BUMPER REINFORCEMENT	Distorted	379.60 FL	*379.60 FL
52	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,670.40 FL	*560.00 FL
53	4		*REVERSE SENSOR HOLDER	Necessary	112.40 FL	*112.40 FL
54	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	865.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*TAILLAMP	Cracked	947.20 FL	*947.20 FL
56	2		*TAILLAMP CHROME MOULDING	Not Necessary	179.20 FL	*- FL
57	2		*TAILLAMP LOWER BRACKET	Not Necessary	208.80 FL	*- FL
58	1		*TAILLAMP PANEL	N/S Dented	575.20 FL	*287.60 FL
59	1		*REAR FENDER	N/S Buckled	2,556.40 FL	*1,278.20 FL
60	2		*REAR FENDER INNER PANEL	Repair	1,530.60 FL	*- FL
61	1		*REAR FENDER AIR VENT LH	Not Necessary	115.40 FL	*- FL
62	2		*REAR FENDER INNER COWLING	Not Necessary	338.80 FL	*- FL
63	2		*REAR FENDER INNER TRIM	Not Necessary	1,050.00 FL	*- FL
64	2		*REAR WHEEL HOUSE PANEL	Repair	1,957.20 FL	*- FL
65	1		*REAR FUEL TANK INLET PIPE	Not Necessary	375.80 FL	*- FL
66	1		*REAR FUEL TANK INLET PIPE HOLDER GARNISH	Not Necessary	86.10 FL	*- FL
67	1		*REAR FUEL TANK INLET PIPE COVER PANEL	Not Necessary	113.60 FL	*- FL
68	1		*REAR FUEL TANK INLET PIPE COVER PANEL LOCK C/W CABLE	Not Necessary	265.60 FL	*- FL
69	2		*REAR DRAIN PANEL	Not Necessary	427.00 FL	*- FL
70	1		*REAR WINDSCREEN MOULDING	Necessary	121.30 FL	*121.30 FL
71	1		*BOOTLID	Distorted	892.40 FL	*892.40 FL
72	2		*BOOTLID HINGE	Bent	236.60 FL	*236.60 FL
73	1		*BOOTLID CHROME MOULDING (CENTRE)	Cracked	356.20 FL	*356.20 FL
74	2		*BOOTLID STOPPER	Not Necessary	38.40 FL	*- FL
75	2		*BOOTLID LAMP	Cracked	653.40 FL	*653.40 FL
76	1		*BOOTLID INSULATOR	Crumpled	294.30 FL	*294.30 FL
77	1		*BOOTLID EMBLEM CAMRY	Necessary	65.00 FL	*65.00 FL
78	1		*BOOTLID EMBLEM 2.5	Necessary	60.00 FL	*60.00 FL
79	1		*BOOTLID LOGO	Necessary	75.00 FL	*75.00 FL
80	1		*BOOTLID LOCK	Damaged	271.40 FL	*271.40 FL
81	1		*BOOTLID CATCHER	Not Necessary	25.00 FL	*- FL
82	1		*BOOTLID WEATHERSTRIP	Cut	227.20 FL	*227.20 FL
83	1		*BOOTLID DETECTOR	Damaged	198.60 FL	*198.60 FL
84	1		*BOOTLID DETECTOR WIRE HARNESS	Not Necessary	396.70 FL	*- FL
85	1		*REVERSE CAMERA	Not Necessary	1,094.20 FL	*- FL
86	1		*REAR END PANEL	Distorted	670.80 FL	*670.80 FL
87	1		*REAR END PANEL TOP GARNISH	Deformed	403.70 FL	*403.70 FL
88	1		*REAR FLOOR PANEL	Buckled	818.70 FL	*818.70 FL
89	2		*REAR FLOOR SIDE PANEL	Repair	1,092.60 FL	*- FL
90	1		*REAR FLOOR PANEL TOP BOARD	Deformed	472.10 FL	*472.10 FL
91	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	438.70 FL	*438.70 FL
92	2		*REAR FLOOR TOP SPONGE (SIDE)	Deformed	397.60 FL	*397.60 FL
93	1		*REAR FLOOR TOP SPONGE (CENTER)	Deformed	312.90 FL	*312.90 FL
94	1		*REAR SPARE TYRE BOLT	Bent	38.10 FL	*38.10 FL
95	1		*REAR CHASSIS MEMBER RH	Repair	1,438.60 FL	*- FL
96	1		*REAR EXHAUST INSULATOR	Not Necessary	109.80 FL	*- FL
97	1		*REAR EXHAUST PIPE	Not Necessary	989.40 FL	*- FL
98	4		*REAR EXHAUST MOUNTING	Not Necessary	156.80 FL	*- FL
99	1		*REAR EXHAUST GASKET	Not Necessary	60.10 FL	*- FL
100	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
101	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
102	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
103	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
104	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
105	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
106	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
107	1		*SET BOOTLID INSULATOR CLIP	Necessary	60.00 FS	*30.00 FS
108	1		*SET TAILLAMP CLIPS	Necessary	30.00 FS	*20.00 FS
109	2		*TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
110	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*60.00 FS
111	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
112	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
113	1		*REAR WHEEL HOUSE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
114	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
115	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
116	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
117	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	350.00 FS	*200.00 FS
118	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
119	1		*REAR EXHAUST CHROME (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	52,752.50	23,975.20
- List Item Discount on L Items 25.00/25.00% (\$)	12,613.13	5,826.30
Total Parts (\$)	40,139.37	18,148.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
3	REFOCUS HEADLAMP BEAM	New	60.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS	New	250.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	PANEL BEATING REMOVAL AND REPLACING PARTS	New	4,800.00	1,600.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,800.00	1,400.00
8	TUFF COAT	New	250.00	120.00
9	WIRING CHECK	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	120.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
14	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
15	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
16	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
17	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	120.00	60.00
18	REAR CHASSIS ALIGNMENT	New	250.00	0.00
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	250.00	0.00
Gross Labour Cost (\$\$)			13,510.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >