

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance Management)
Singapore 068897

Our File No: CS/AIS23003063/TVY3Q2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant:	CITY CONTAINER (S) PTE. LTD.	Policy No:	SP2002755946
Date of Loss:	10/03/2023	Nature of Claim:	OD Claim No: 202332006202

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE3469B		
Make & Model:	UD TRUCKS GKB5ALDHCQA, 7.5 D (M)	Engine No:	GH11743075
Reg. Date:	25/09/2017 (Man. Year: 2017)	Chassis No:	JNCM1F1AXHU020361
Colour:	Yellow	Odometer:	0 km
Engine Capacity:	10837 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	Gold Shield 8 mm	Rear Left Side:	Gold Shield 8/8 mm
Front Right Side:	Gold Shield 8 mm	Rear Right Side:	Gold Shield 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,580.00	11,709.50	14,870.50	55.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	3,570.00	1,160.00	24.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,310.00	15,279.50	16,030.50	51.20
Approved Total (Overridden) (\$\$)		7,000.00		
- Excess (\$\$)	0.00	2,500.00	-2,500.00	
(\$\$)	31,310.00	4,500.00	26,810.00	85.63
+ GST 8.00/8.00% (\$\$)	2,504.80	360.00	2,144.80	85.63
Nett Amount (\$\$)	33,814.80	4,860.00	28,954.80	85.63

INSPECTION

Date of Assignment:	23/03/2023 Present Location:	ASM Automotive Services Pte Ltd (HQ) BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457
Date Inspected:	24/03/2023 Inspected At:	Repairer:ASM Automotive Services Pte Ltd (HQ)
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jul 2023)	
Parts:	N/A	UD TRUCKS GKB5ALDHCQA 7.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE3469B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (CTR) (WCP)	Bent	485.00 F	*485.00 F
2	1		*FRT BUMPER (RH) (WCP)	Bent	400.00 F	*400.00 F
3	1		*FRT BUMPER REINFORCEMENT (WCP)	Not Necessary	750.00 F	*- F
4	1		*FRT BUMPER LOWER GRILLE (WCP)	Missing	130.00 F	*130.00 F
5	1		*FRT HEADLAMP (RH) (WCP)	Cracked	600.00 F	*600.00 F
6	1		*FRT FOGLAMP (RH) (WCP)	Cracked	100.00 F	*100.00 F
7	1		*FRT SIGNAL LAMP (RH) (WCP)	Cracked	50.00 F	*50.00 F
8	1		*FRT BUMPER SIDE (RH) (WCP)	Bent	55.00 F	*55.00 F
9	1		*FRT PANEL HINGE (RH) (WCP)	Not Necessary	65.00 F	*- F
10	1		*FRT PANEL INNER REINFORCEMENT (WCP)	Not Necessary	700.00 F	*- F
11	1		*FRT PANEL LOWER GRILLE (TOP) (WCP)	Cracked	220.00 F	*220.00 F
12	1		*FRT PANEL LOWER GRILLE (BOTTOM) (WCP)	Cracked	240.00 F	*240.00 F
13	1		*FRT PANEL LOCK (WCP)	Not Necessary	60.00 F	*- F
14	1		*FRT PANEL LOCK CABLE (WCP)	Not Necessary	110.00 F	*- F
15	1		*FRT PANEL LOCK LATCH (WCP)	Not Necessary	25.00 F	*- F
16	1		*FRT CORNER PANEL (RH) (WCP)	Bent	335.00 F	*335.00 F
17	1		*FRT WINDSCREEN (WCP)	Not Necessary	950.00 F	*- F
18	1		*FRT WINDSCREEN RUBBER (WCP)	Necessary	310.00 F	*310.00 F
19	1		*FRT WINDSCREEN ERP BRACKET	Not Necessary	26.00 FS	*- FS
20	1		*FRT WINDSCREEN PILLAR (WCP)	Bent	1,400.00 F	*1,400.00 F
21	1		*FRT WINDSCREEN PILLAR INNER (RH) (WCP)	Not Necessary	900.00 F	*- F
22	1		*FRT WINDSCREEN PILLAR INNER TRIM (RH) (WCP)	Not Necessary	140.00 F	*- F
23	1		*FRT STEP ALLOY (RH)(LOWER) (WCP)	Buckled	180.00 F	*180.00 F
24	1		*FRT STEP GARNISH (RH)(LOWER) (WCP)	Cracked	80.00 F	*80.00 F
25	1		*FRT STEP ALLOY (RH)(TOP) (WCP)	Buckled	180.00 F	*180.00 F
26	1		*FRT STEP GARNISH (RH)(TOP) (WCP)	Cracked	350.00 F	*350.00 F
27	1		*FRT STEP BRACKET @FRT (WCP)	Bent	320.00 F	*320.00 F
28	1		*FRT STEP BRACKET @RR (WCP)	Bent	320.00 F	*320.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*FRT STEP GRANISH COVER (RH) (WCP)	Missing	45.00 F	*45.00 F
30	1		*FRT WHEEL ARCH PANEL (RH) (WCP)	Bent	495.00 F	*495.00 F
31	1		*FRT WHEEL ARCH GARNISH (RH) (WCP)	Deformed	390.00 F	*390.00 F
32	1		*FRT WHEEL ARCH PROTECTOR (RH) (WCP)	Deformed	270.00 F	*270.00 F
33	1		*FRT WHEEL ARCH STEP (RH) (WCP)	Not Necessary	60.00 F	*- F
34	1		*FRT WHEEL SCUFF PLATE (WCP)	Not Necessary	130.00 F	*- F
35	1		*FRT WHEEL ARCH INNERSHIELD (RH) (WCP)	Deformed	170.00 F	*170.00 F
36	1		*FRT WHEEL ARCH INNERSHIELD (TOP) (WCP)	Deformed	180.00 F	*180.00 F
37	1		*FRT DOOR RH (WCP)	Bent	2,100.00 F	*2,100.00 F
38	1		*FRT DOOR HINGE (RH) (WCP)	Bent	65.00 F	*65.00 F
39	1		*FRT DOOR TRIMBOARD (RH) (WCP)	Not Necessary	350.00 F	*- F
40	1		*FRT DOOR RUBBER (WCP)	Necessary	195.00 F	*195.00 F
41	1		*FRT DOOR GK420 STICKER (WCP)	Necessary	80.00 F	*80.00 F
42	1		*FRT DOOR LOCK (RH) (WCP)	Not Necessary	275.00 F	*- F
43	1		*FRT DOOR LAMP (RH) (WCP)	Not Necessary	105.00 F	*- F
44	1		*FRT DOOR CHECKER (RH) (WCP)	Not Necessary	185.00 F	*- F
45	1		*FRT DOOR INNER MOULDING (WCP)	Not Necessary	185.00 F	*- F
46	1		*FRT DOOR GLASS REGULATOR (WCP)	Not Necessary	245.00 F	*- F
47	1		*FRT DOOR GLASS MOTOR (WCP)	Not Necessary	335.00 F	*- F
48	1		*FRT DOOR GLASS RUN CHANNEL (WCP)	Not Necessary	210.00 F	*- F
49	1		*FRT DOOR GLASS INNER MOULDING (WCP)	Not Necessary	185.00 F	*- F
50	1		*FRT DOOR PANEL (RH) (WCP)	Buckled	900.00 F	*900.00 F
51	1		*FRT DOOR PANEL INNERTRIM (RH) (WCP)	Not Necessary	280.00 F	*- F
52	1		*STEERING BOX (WCP)	Not Necessary	2,100.00 F	*- F
53	1		*FRT DASHBOARD (WCP)	Not Necessary	2,300.00 F	*- F
54	1		*FRT SUPPORT BEAM (WCP)	Not Necessary	1,200.00 F	*- F
55	1		*ACCELERATOR ASSY (WCP)	Not Necessary	850.00 F	*- F
56	1		*BRAKE PEDAL ASSY (WCP)	Not Necessary	750.00 F	*- F
57	1		*FRT PANEL LOCK (RH) (WCP)	Not Necessary	50.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	24,166.00	10,645.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	2,414.00	1,064.50
Total Parts (\$\$)	26,580.00	11,709.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REMOVE & REPLACE ABOVE PARTS	New	2,000.00	1,600.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	2,200.00	1,700.00
3	TO REMOVE & REFIX FRT DOOR GLASS (RH)	New	80.00	80.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	250.00	0.00
5	TO REMOVE & REPLACE FRT WINDSCREEN	New	150.00	150.00
6	TO CHECK WIRING	New	50.00	40.00
Gross Labour Cost (S\$)			4,730.00	3,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >