

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

HL Assurance Pte Ltd  
11 Keppel Road, #11-01 ABI Plaza  
Singapore 089057

**Our File No:** CS/HLA23003065/UNY3Q2**Date:** 11/07/2023**REFERENCE**

Insured/Claimant:	PEH TEOW PENG	Policy No:	MP321312		
Date of Loss:	18/03/2023	Nature of Claim:	OD	Claim No:	MPC04062

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNE4381G</b>	Engine No:	L15B6562146
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB53101858
Reg. Date:	15/03/2022 (Man. Year: 2019)	Odometer:	6426 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,385.50	1,243.00	4,142.50	76.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,530.00	1,270.00	45.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,185.50</b>	<b>2,773.00</b>	<b>5,412.50</b>	<b>66.12</b>
<b>- Excess (\$\$)</b>	300.00	300.00	0.00	0.00
<b>(\$\$)</b>	7,885.50	2,473.00	5,412.50	68.64
<b>+ GST 8.00/8.00% (\$\$)</b>	630.84	197.84	433.00	68.64
<b>Nett Amount (\$\$)</b>	<b>8,516.34</b>	<b>2,670.84</b>	<b>5,845.50</b>	<b>68.64</b>

**INSPECTION**

Date of Assignment:	24/03/2023 Present Location:	Abwin Service Pte Ltd (HQ) Abwin Service Pte Ltd (HQ) 17 Kaki Bukit Road 4, Bartley Biz Centre #01-58/59/60/61/62 Singapore 417809
Date Inspected:	31/03/2023 Inspected At:	
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
<b>Parts:</b>	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNE4381G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT DOOR RH</b> (WCP)	Badly Dented	620.00 F	*550.00 F
2	1		<b>*FRONT DOOR HINGE UPPER RH</b> (WCP)	Not Necessary	40.00 F	*- F
3	1		<b>*FRONT DOOR HINGE LOWER RH</b> (WCP)	Not Necessary	40.00 F	*- F
4	1		<b>*FRONT DOOR HANDLE RH</b> (WCP)	Not Necessary	300.00 F	*- F
5	1		<b>*FRONT DOOR REGULATOR RH</b> (WCP)	Not Necessary	370.00 F	*- F
6	1		<b>*DOOR PILLAR RH</b> (WCP)	Repair	610.00 F	*- F
7	1		<b>*REAR SLIDING DOOR RH</b> (WCP)	Badly Dented	650.00 F	*580.00 F
8	1		<b>*REAR SLIDING DOOR HINGE UPPER RH</b> (WCP)	Not Necessary	85.00 F	*- F
9	1		<b>*REAR SLIDING DOOR HINGE LOWER RH</b> (WCP)	Not Necessary	210.00 F	*- F
10	1		<b>*REAR SLIDING DOOR HANDLE RH</b> (WCP)	Not Necessary	300.00 F	*- F
11	1		<b>*REAR SLIDING DOOR REGULATOR RH</b> (WCP)	Not Necessary	380.00 F	*- F
12	1		<b>*REAR SLIDING DOOR ROLLER RH</b> (WCP)	Not Necessary	250.00 F	*- F
13	1		<b>*REAR FENDER RH</b> (WCP)	Repair	690.00 F	*- F
14	1		<b>*ROCKER PANEL RH</b> (WCP)	Repair	200.00 F	*- F
15	1		<b>*REAR DOOR GLASS MOUDLING RH</b> (WCP)	Not Necessary	60.00 F	*- F
16	1		<b>*DOOR CLIPS</b>	Not Necessary	50.00 FS	*- FS
17	1		<b>*ROCKER PANEL CLIPS</b>	No such part	50.00 FS	*- FS

F=Franchise part, S=SpcNett.

Sub Total (\$\$)	4,905.00	1,130.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	480.50	113.00
<b>Total Parts (\$\$)</b>	<b>5,385.50</b>	<b>1,243.00</b>

[https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\\_printprt&caseid=1216847&extid=413708&CFID=10806...](https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=1216847&extid=413708&CFID=10806...) 2/3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,000.00	600.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
3	TO APPLY UNDERCOATING FOR RUST PROOFING	New	180.00	0.00
4	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT RH DOOR COMPONENTS	New	150.00	50.00
5	TO DISMANTLE, REPLACE AND/OR REPAIR REAR RH DOOR COMPONENTS	New	150.00	60.00
6	TO CHECK WIRING	New	120.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,800.00</b>	<b>1,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >