



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2598T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	TO REPAIR SEE LABOUR	586.18	-
2	FRT BUMPER BRACKET LH / RH @\$77.00	NOT NECESSARY	154.00	-
10	FRONT BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	86.50	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	88.00	-
1	FRONT HEAD LAMP LH	NOT NECESSARY	2,637.60	-
1	FRONT BUMPER DAY RUNNING LH	NOT NECESSARY	920.00	-
	LESS 25% DISCOUNT		-1,123.57	-
			3,370.71	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER COVER.		550.00	350.00
	SPRAY PAINTING.		300.00	250.00
	TUFF COAT.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	30.00
			970.00	630.00
<b>GRAND TOTAL</b>			<b>4,340.71</b>	<b>630.00</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>630.00</b>

Report Ref No. NS/INC23003071/Svp3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.