

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3444S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	CRACKED	586.18	586.18
1	FRONT BUMPER LOWER REINFORCEMENT RH	NOT NECESSARY	364.20	-
1	FRONT BUMPER SIDE SUPPORT RH	NOT NECESSARY	90.75	-
1	FOGLAMP RH	BROKEN	920.00	920.00
1	HEADLAMP RH	SCRATCHED	2,637.60	2,637.60
1	HEADLAMP PANEL RH	DENTED	240.10	240.10
1	ROCKER PANEL GARNISH RH	TO REPAIR SEE LABOUR	576.00	-
1	FRONT FENDER (HYBRID) RH	NECESSARY	86.50	86.50
1	FRONT FENDER SHIELD RH	NOT NECESSARY	198.50	-
1	FRONT WHEEL APRON RH	NOT NECESSARY	958.30	-
1	WIPER WASHER TANK WITH MOTOR	DENTED	486.70	486.70
1	FRONT WHEEL CAP RH	SCRATCHED	189.60	189.60
	LESS 25% DISCOUNT		-1,833.61	-1,286.67
			5,500.82	3,860.01
	SPECIAL NETT ITEMS			
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	216.00	-
1	FRONT FENDER ADV.STICKER RH (SN)	NECESSARY	100.00	100.00
			316.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROCKER PANEL GARNISH RH.		1,200.00	1,050.00
	SPRAY PAINTING CHARGE - WING MIRROR RH ETC.		1,000.00	750.00
	WIRING CHARGE.		60.00	30.00
	TUFF KOTE.		60.00	30.00
	WHEEL ALIGNMENT.		120.00	40.00
	TOWING CHARGE.		60.00	-
			2,500.00	1,900.00
	GRAND TOTAL		8,316.82	5,860.01

Report Ref No. NS/INC23003072/Swp3e2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,700.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC23003072/Swp3e2

//

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser