

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8808T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID COVER	DENTED / BUCKLED	2,329.38	2,329.38
1	BOOTLID LOCK	NOT NECESSARY	273.40	-
1	BOOTLID EMBLEM - STAR	NECESSARY	45.46	45.46
1	REAR SIDE BUMPER LH	NOT NECESSARY	473.60	-
1	TAILLAMP ASSY LH	CRACKED	622.44	622.44
1	REAR BUMPER ASSY	BROKEN	1,372.00	1,372.00
1	REAR BUMPER REINFORCEMENT	DENTED	462.48	462.48
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	BUMPER REINFORCEMENT BRACKET LH	NOT NECESSARY	141.14	-
1	BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	141.14	-
1	REAR WINDSCREEN GLASS	BROKEN	1,273.98	1,273.98
	LESS 20% DISCOUNT		-1,431.40	-1,225.55
			5,725.62	4,902.19
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SCRATCHED	80.00	80.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	BOOTLID MAXI LOGO (SN)	NECESSARY	80.00	80.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	288.00	-
			494.00	206.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,200.00	800.00
	SPRAY PAINT.		600.00	500.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			2,100.00	1,470.00
	GRAND TOTAL		8,319.62	6,578.19

Report Ref No. NS/INC23003074/Svp3e2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,250.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. NS/INC23003074/Svp3e2

//

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser