



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5575P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT LH FENDER (WCP)	BADLY DENTED	195.00	195.00
1	FRT LH FENDER INNER COWLING (WCP)	SERVICEABLE	75.00	-
10	INNER COWLING CLIP (WCP)	NOT NECESSARY	20.00	-
	COST PLUS 10%		29.00	19.50
			319.00	214.50
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	WHEEL ALIGNMENT.		80.00	60.00
	LABOUR CHARGE.		450.00	200.00
	SPRAY PAINTING (PEARL).		500.00	500.00
			1,060.00	780.00
	GRAND TOTAL		1,379.00	994.50
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			994.50

Report Ref No. CS/SMO23003080/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.