

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI22005151/TWP3E2-1**Date:** 04/04/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00009832100
Claimant Vehicle No :	SKP8073Y	Insured Vehicle No :	SLC9854K
Date of Loss:	29/05/2022	Nature of Claim: TP	Claim No: SNM22D203764/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8073Y	Engine No:	27091030453973
Make & Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Chassis No:	WDD1760422J300124
Reg. Date:	14/10/2014 (Man. Year: 2014)	Odometer:	136525 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,181.27	4,130.93	2,050.34	33.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	918.00	620.00	298.00	32.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,099.27	4,750.93	2,348.34	33.08
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	7,099.27	3,800.00	3,299.27	46.47
+ GST 8.00/8.00% (S\$)	567.94	304.00	263.94	46.47
Nett Amount (S\$)	7,667.21	4,104.00	3,563.21	46.47

INSPECTION

Date of Assignment:	31/05/2022		
Date Inspected:	31/05/2022	Inspected At:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2023)
Parts:	144	MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8073Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,389.20 FL	*1,389.20 FL
2	1		*FRONT BUMPER EMBLEM	Necessary	63.80 FL	*63.80 FL
3	1		*FRONT BUMPER RETAINER LH	Torn	130.00 FL	*130.00 FL
4	1		*FRONT BUMPER PARKING SENSOR (4PCS)	Malfunction(2Pcs Only)	938.00 FL	*469.00 FL
5	1		*FRONT BUMPER SIDE GRILLE LH	Torn	48.12 FL	*48.12 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	130.36 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE SIDE BRACKET LH	Torn	55.00 FL	*55.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	368.90 FL	*- FL
9	1		*FRONT BUMPER NUMBER PLATE HOLDER	Deformed	87.73 FL	*87.73 FL
10	1		*CENTER GRILLE	Cracked	604.80 FL	*460.00 FL
11	1		*CENTER GRILLE EMBLEM	Necessary	139.32 FL	*139.32 FL
12	1		*HEADLAMP LH	Cracked	1,009.60 FL	*1,009.60 FL
13	1		*RADAR SENSOR BRACKET	Fractured	38.60 FL	*38.60 FL
14	1		*RADAR SENSOR	Not Necessary	1,126.20 FL	*- FL
15	1		*FRONT NUMBER PLATE WITH CASING	Bent	60.00 FS	*45.00 FS
16	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*FRONT BUMPER LOWER SPOILER	Cut / Torn	326.60 FS	*326.60 FS
18	1		*SET FRONT BUMPER SIDE FLAP	Deformed	228.00 FS	*228.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,794.23	4,519.97
- List Item Discount on L Items 10.00/10.00% (\$\$)	612.96	389.04
Total Parts (\$\$)	6,181.27	4,130.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	540.00	300.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	250.00	250.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	20.00	0.00
4	REMOVE AND REPLACE FRONT BUMPER SENSOR	New	76.50	40.00
5	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	31.50	30.00
Gross Labour Cost (S\$)			918.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >