

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003091/UPA3Q2**Date:** 23/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462199
Claimant Vehicle No :	PC929R	Insured Vehicle No :	EK8782G
Date of Loss:	23/03/2023	Nature of Claim:	TP
		Claim No:	5583170354SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC929R	Engine No:	64698051512122
Make & Model:	MERCEDES-BENZ VITO 115E, 2.1 D EU4 (A)	Chassis No:	WDF63970523404144
Reg. Date:	20/05/2008 (Man. Year: 2008)	Odometer:	508790 km
Colour:	Black		
Engine Capacity:	2148 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,759.00	5,815.60	943.40	13.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,720.00	380.00	18.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,859.00	7,535.60	1,323.40	14.94
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	8,859.00	6,000.00	2,859.00	32.27
+ GST 8.00/8.00% (S\$)	708.72	480.00	228.72	32.27
Nett Amount (S\$)	9,567.72	6,480.00	3,087.72	32.27
+ Car Rental (6.0 x S\$120.00/day + 8.00% GST) (S\$)		777.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,259.60		
Global Sum Settlement (S\$)		7,250.00		

INSPECTION

Date of Assignment:	24/03/2023	
Date Inspected:	24/03/2023	Inspected At: Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.00 F	*2,051.00 FL
2	1		*REAR BOOT GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
3	1		*REAR BOOT MOULDING	No such part	90.00 F	*- FL
4	1		*REAR BOOT LOGO	Necessary	68.00 F	*68.00 FL
5	1		*REAR BOOT VITO WORDING	Necessary	82.00 F	*82.00 FL
6	1		*REAR BOOT 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
7	1		*REAR BOOT LICENCE PLATE	Serviceable	40.00 FS	*- FS
8	1		*REAR BOOT CDI WORDING	Necessary	58.00 F	*58.00 FL
9	1		*REAR BOOT HANDLE	Serviceable	185.00 F	*- FL
10	1		*REAR BOOT LOCK	Twisted / Jammed	266.00 F	*266.00 FL
11	1		*REAR BOOT INNER TRIM BOARD	Deformed / Torn	641.00 F	*641.00 FL
12	1		*REAR BUMPER	Distorted	945.00 F	*945.00 FL
13	1		*REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
14	1		*REAR BUMPER INNER BRACKET	Cracked	213.00 F	*213.00 FL
15	1		*WHETHER STRIPE	Twisted	288.00 F	*288.00 FL
16	1		*REAR END PANEL	Badly Dented	645.00 F	*645.00 FL
17	1		*REAR END PANEL GARNISH	Twisted	281.00 F	*281.00 FL
18	1		*RIGHT TAILLAMP	Cracked	321.00 F	*321.00 FL
19	1		*REAR BUMPER SIDE N/S	Deformed / Torn	325.00 F	*325.00 FL
					Sub Total (S\$)	6,759.00 6,434.00
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 618.40
					Total Parts (S\$)	6,759.00 5,815.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR BOOT GLASS	New	150.00	120.00
2	TRANSFER BOOT	New	150.00	60.00
3	ANTI RUST PROOF	New	100.00	60.00
4	CHECK WIRING	New	100.00	20.00
5	PANEL BEATING	New	800.00	680.00
6	PAINT WORK	New	800.00	780.00
Gross Labour Cost (S\$)			2,100.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >