

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123003095/AVY3M4**Date:** 10/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** GBF6789M **Insured Vehicle No :** PA7827R

Date of Loss: 22/03/2023 Nature of Claim: TP Claim No: CDMCG23000729

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBF6789M**

Make & Model: KIA K2500 6M/T, 2.5 D (M) Engine No: D4CBE571248

Reg. Date: 30/03/2015 (Man. Year: 2014) Chassis No: KNCSJX76LF7907535

Colour: Green Odometer: 260994 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C

Front Left Side: Bridgestone 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,471.52	3,091.85	1,379.67	30.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,230.00	710.00	36.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,411.52</b>	<b>4,321.85</b>	<b>2,089.67</b>	<b>32.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,450.00</b>		
<b>(S\$)</b>	6,411.52	3,450.00	2,961.52	46.19
<b>+ GST 8.00/8.00% (S\$)</b>	512.92	276.00	236.92	46.19
<b>Nett Amount (S\$)</b>	<b>6,924.44</b>	<b>3,726.00</b>	<b>3,198.44</b>	<b>46.19</b>

**INSPECTION**

Date of Assignment: 24/03/2023

Date Inspected: 03/04/2023 Inspected At: TWINCAR AUTOMOTIVE PTE LTD  
2 KAKI BUKIT AVE 2  
#01-17 KAKI BUKIT AUTOHUB  
SINGAPORE 417921

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jul 2023)	
Parts:	N/A	KIA K2500 6M/T 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6789M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Dented	385.70 FL	*385.70 FL
2	1		*REAR NUMBER PLATE BRACKET HOLDER	Bent	125.30 FL	*125.30 FL
3	1		*REAR NUMBER PLATE LAMP	Damaged	168.00 FL	*168.00 FL
4	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	469.70 FL	*- FL
5	1		*REAR TAILGATE	Dented	1,268.70 FL	*1,268.70 FL
6	3		*REAR TAILGATE HINGES	Not Necessary	397.20 FL	*- FL
7	1		*REAR TAILGATE SIDE LOCK L/R	N/S Dented	197.40 FL	*98.70 FL
8	2		*REAR TAILLAMP L/R	Cracked	391.40 FL	*391.40 FL
9	1		*REAR TAILLAMP PANEL L/R	O/S Dented	517.40 FL	*258.70 FL
10	4		*REAR TAILLAMP PANEL RUBBER STOPPER L/R	Not Necessary	42.00 FL	*- FL
11	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
12	1		*REAR NUMBER PLATE FRAME	Deformed	50.00 FS	*30.00 FS
13	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
14	1		*REAR STEP PANEL	Bent	250.00 FS	*200.00 FS
15	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
16	1		*REAR TAILGATE 7PAX STICKER	Necessary	25.00 FS	*15.00 FS
17	1		*REAR TAILGATE DECAL STICKER	Necessary	250.00 FS	*180.00 FS
					Sub Total (S\$)	4,867.80 3,361.50
					- List Item Discount on L Items 10.00/10.00% (S\$)	396.28 269.65
					Total Parts (S\$)	4,471.52 3,091.85

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	500.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	600.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	50.00
5	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUCNTION	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,940.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >