

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003107/UPA3Q2**Date:** 05/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700055382-05
Claimant Vehicle No :	CB7463E	Insured Vehicle No :	SLS4077K
Date of Loss:	22/03/2023	Nature of Claim:	TP
		Claim No:	7593471124SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB7463E		
Make & Model:	TOYOTA HIACE 3.0 DX DIESEL TBO AT 2WD, 3.0 D (A)	Engine No:	1KD2407265
Reg. Date:	10/11/2014 (Man. Year: 2014)	Chassis No:	KDH2010145934
Colour:	Silver	Odometer:	266909 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,934.74	30.00	1,904.74	98.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	640.00	1,730.00	73.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,304.74	670.00	3,634.74	84.44
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		896.75		

INSPECTION

Date of Assignment:	28/03/2023	
Date Inspected:	28/03/2023	Inspected At: Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHEEL BEARING (R/H/F)	Not Necessary	351.95 FL	*- FL
2	1		*SHOCK ABSORBER (R/H/F)	Not Necessary	130.43 FL	*- FL
3	1		*LOWER ARM (R/H/F)	Not Necessary	437.14 FL	*- FL
4	1		*FENDER (R/H/R)	Repair	1,086.80 FL	*- FL
5	1		*STICKER SCHOOL BUS	Necessary	30.00 FS	*30.00 FS
6	1		*TYRE (R/H/R)	Not Necessary	220.00 FS	*- FS
7	1		*RIM	Not Necessary	180.00 FS	*- FS
					Sub Total (\$\$)	2,436.32 30.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	501.58 0.00
					Total Parts (\$\$)	1,934.74 30.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & REPLACING OF THE ABOVE	New	1,000.00	200.00
2	TO PUTTY AND RESPRAY AFFECTED PORTION	New	600.00	380.00
3	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	New	120.00	60.00
4	TO APPLY UNDERCOATING TO ABOVE AFFECTED	New	120.00	0.00
5	TO CHECK UNDERCARRIAGE AND REPALCE DAMAGED PARTS	New	350.00	0.00
6	TO REMOVE AND REFIT COMPONENTS /FACILITATE THE REPAIR	New	180.00	0.00
Gross Labour Cost (S\$)			2,370.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >