

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23003111/UWP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00119462200		
Claimant Vehicle No :	SLX5113G	Insured Vehicle No :	SNE117E		
Date of Loss:	12/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202254/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLX5113G</b>	Engine No:	G4NAHA676212
Make & Model:	HYUNDAI LF SONATA, 2.0 GLS A/T (A)	Chassis No:	KMHE341CMJA435571
Reg. Date:	29/03/2018 (Man. Year: 2017)	Odometer:	55794 km
Colour:	Blue		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,393.60	0.00	2,393.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	870.00	300.00	570.00	65.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,263.60</b>	<b>300.00</b>	<b>2,963.60</b>	<b>90.81</b>
<b>+ GST 8.00/8.00% (S\$)</b>	261.09	24.00	237.09	90.81
<b>Nett Amount (S\$)</b>	<b>3,524.69</b>	<b>324.00</b>	<b>3,200.69</b>	<b>90.81</b>

**INSPECTION**

Date of Assignment:	31/03/2023	3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977 Repairer:Hock Wah Motor Workshop Pte Ltd (HQ)
Date Inspected:	08/05/2023 Inspected At:	
Estimated Period of Repair:	1.0 days	

**Adjuster:** MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	HYUNDAI LF SONATA 2.0 GLS A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX5113G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Repair	2,772.00 FL	*- FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	25.00 FL	*- FL
3	1		*FRONT BUMPER PARKING SENSOR RH	Not Necessary	195.00 FL	*- FL
4	1		*FRONT BUMPER (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,992.00	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)	598.40	0.00
Total Parts (S\$)	2,393.60	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	300.00	100.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	200.00
3	ANTI-RUST COATING	New	80.00	0.00
4	WIRING	New	40.00	0.00
5	TO REMOVE & REFIT PARKING SENSOR	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>870.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >