

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23003113/HVP3M4**Date:** 09/05/2023**REFERENCE**

Insured/Claimant:	HU CHENG CHEN	Policy No:	SP2004285087-01	
Date of Loss:	22/03/2023	Nature of Claim:	OD	Claim No: 202332006466

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLW7719B</b>		
Make & Model:	VOLVO S60, 1.5 T2 (A)	Engine No:	B4154T52362851
Reg. Date:	28/02/2018 (Man. Year: 2017)	Chassis No:	YV1FS28L0J2461016
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,908.50	1,908.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	800.00	350.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,058.50</b>	<b>2,708.50</b>	<b>350.00</b>	<b>11.44</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,850.00</b>		
<b>(\$\$)</b>	3,058.50	1,850.00	1,208.50	39.51
<b>+ GST 8.00/8.00% (\$\$)</b>	244.68	148.00	96.68	39.51
<b>Nett Amount (\$\$)</b>	<b>3,303.18</b>	<b>1,998.00</b>	<b>1,305.18</b>	<b>39.51</b>

**INSPECTION**

Date of Assignment:	27/03/2023	Present Location:	City Auto Pte Ltd (HQ)
Date Inspected:	27/03/2023	Inspected At:	City Auto Pte Ltd (HQ) 160 Sin Ming Drive #05-01,, Sin Ming AutoCity, Singapore 575722
Estimated Period of Repair:	4.0 days		

**Adjuster:** Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2023)
Parts:	143	VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW7719B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Headlamp RH (WCP)	Cut	950.00 F	*950.00 F
2	1		*Front fender RH (WCP)	Buckled	700.00 F	*700.00 F
3	1		*Front bumper retainer RH (WCP)	Distorted	85.00 F	*85.00 F
F=Franchise part.						
Sub Total (\$)					1,735.00	1,735.00
+ Margin on L,N Items 10.00/10.00% (\$)					173.50	173.50
Total Parts (\$)					1,908.50	1,908.50
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	450.00	300.00
2	- Spray painting on affected and replace parts	New	700.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,150.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >