

ASS. REC. BY:

REF:

AGZ/ 23003115/KC

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/IV

To Inspect Vehicle No:

at Workshop m/s

Pulco

of

3086

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 8304G

Yr Regn:

08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M17 outlander

C.C.

Wagon 1998

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

60080

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GIF 7W . 0700666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko

R: TOYO

225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/3/23

Rear

R/Bal.

7

mm

L/Bal.

7

mm

D.O.I.

27/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA & EN not ready

28/7 11:00 & 3850h Calm (Red. 8440.38, 68%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

83850

TOTAL

Fulco Autocare Pte Ltd

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721

Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: fulco0302@gmail.com

Make/Model: MITSUBISHI OUTLANDER

Engine/Chassis No.: GF7W0700666


Date of accident: 23.03.23

Damaged area: Rear

Date: 28/03/2023

Claim Type: TP

VRN: SMU8304G



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>85Z</i>	<i>By</i> 1	\$ 1,323.20	\$ 1,323.20
2	Rear bumper lower <i>292</i>	<i>By</i> 1	\$ 547.00	\$ 547.00
3	Rear bumper reflector lamp <i>0245-10 N11 CM</i>	2	\$ 323.00	\$ 646.00
4	Rear bumper lower silver moulding <i>NJP</i>	1	\$ 389.00	\$ 389.00
5	Rear bumper reflector inner bracket	2	\$ 36.00	\$ 72.00
6	Rear bumper side retainer <i>M1 D11</i>	2	\$ 65.00	\$ 130.00
7	Rear bumper reinforcement <i>312</i>	<i>By</i> 1	\$ 594.00	\$ 594.00
8	Rear bumper impact absorber LH/RH <i>N11 M</i>	2	\$ 115.00	\$ 230.00
9	Rear bumper tow cover	1	\$ 41.00	\$ 41.00
10	End panel upper	1	\$ 488.00	\$ 488.00
11	End panel top garnish	1	\$ 177.00	\$ 177.00
12	End panel top bracket	3	\$ 76.00	\$ 228.00
13	Tailgate <i>1025</i>	<i>By</i> 1	\$ 1,959.00	\$ 1,959.00
14	Rear windscreen moulding	<i>NRA1</i>	\$ 135.00	\$ 135.00
15	Tailgate logo <i>75</i>	<i>NRA</i> 1	\$ 105.00	\$ 105.00
16	Tailgate weatherstrip	<i>By</i> 1	\$ 189.00	\$ 189.00
17	Tailgate lock <i>229</i>	<i>NRA</i> 1	\$ 412.00	\$ 412.00
18	Tailgate lock striker	1	\$ 75.00	\$ 75.00
19	Tailgate inner trimboard	1	\$ 577.00	\$ 577.00
20	Tailgate "C&C" emblem <i>80</i>	<i>NRA</i> 1	\$ 88.00	\$ 88.00
21	Tailgate "MIVEC" emblem <i>50</i>	<i>NRA</i> 1	\$ 55.00	\$ 55.00
22	Tailgate "OUTLANDER" emblem	<i>NRA</i> 1	\$ 65.00	\$ 65.00
23	Rear bumper reinforcement bracket	2	\$ 69.00	\$ 138.00
24	Keyless antenna <i>96</i>	<i>CM1</i> 1	\$ 315.00	\$ 315.00
Subtotal			\$	8,978.20
List discount				10.00%
Total			\$	8,080.38

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Reverse sensor	<i>1/10m</i> 1	\$ 280.00	\$ 280.00
2	Rear bumper clips	<i>NRA</i> 12	\$ 5.50	\$ 66.00

Repair Estimate

3	End panel top garnish clips	nn 8	\$ 5.50	\$ 44.00	X
4	Reverse camera	sn 1	\$ 480.00	\$ 480.00	X
5	Tailgate inner trimboard clips	nn 10	\$ 5.50	\$ 55.00	X
6	End panel sealant	nn 1	\$ 100.00	\$ 100.00	X
7	Rear licence plate and frame	sn 1	\$ 55.00	\$ 55.00	X
8	Rear windscreen sealant	nn 1	\$ 80.00	\$ 80.00	40sm
9	Sundries	nn 1	\$ 50.00	\$ 50.00	X
Total				\$ 1,210.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00	500l
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	20l
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00	60l
4	To rust proof all affected portions after repair.	0.5	\$ 100.00	30l
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00	120l
6	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00	660l
Total labour			\$ 3,000.00	

Estimate Grand Total	\$ 12,290.38
-----------------------------	---------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: