

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI23003119/SVY3M4**Date:** 28/06/2023**REFERENCE**

Insured/Claimant:	MIKE WANG CHEOW YONG	Policy No:	DMPG23000485
Date of Loss:	24/03/2023	Nature of Claim:	OD
		Claim No:	CDMPG23000721

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLD7988R</b>		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030769534
Reg. Date:	05/01/2017 (Man. Year: 2016)	Chassis No:	WDD2050402R232856
Colour:	Silver	Odometer:	74170 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,715.50	6,633.00	82.50	1.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	830.00	1,490.00	64.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,035.50</b>	<b>7,463.00</b>	<b>1,572.50</b>	<b>17.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,950.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	8,535.50	5,450.00	3,085.50	36.15
<b>+ GST 8.00/8.00% (S\$)</b>	682.84	436.00	246.84	36.15
<b>Nett Amount (S\$)</b>	<b>9,218.34</b>	<b>5,886.00</b>	<b>3,332.34</b>	<b>36.15</b>

**INSPECTION**

Date of Assignment:	24/03/2023 Present Location:	Forza Autohaus Pte Ltd (HQ) Forza Autohaus Pte Ltd (HQ) No.39 Woodlands Close, #01-34/35, Mega@Woodlands Singapore 737856
Date Inspected:	27/03/2023 Inspected At:	
Estimated Period of Repair:	3.0 days	

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2023)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD7988R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	1,275.00 F	*1,275.00 F
2	1		*FRONT BONNET LOCK (WCP)	Malfunction	225.00 F	*225.00 F
3	1		*FRONT GRILLE ASSY (WCP)	Cracked	650.00 F	*650.00 F
4	1		*FRONT BUMPER (WCP)	Cracked	1,175.00 F	*1,175.00 F
5	1		*FRONT BUMPER CAR PLATE HOLDER (WCP)	Cracked	120.00 F	*120.00 F
6	1		*FRONT BUMPER TOW COVER (WCP)	Not Necessary	75.00 F	*- F
7	1		*FRONT BUMPER CAR PLATE SET (WCP)	Cracked	60.00 F	*60.00 F
8	1		*FRONT HEADLAMP RH (WCP)	Broken	2,250.00 F	*2,250.00 F
9	1		*FRONT MOUNTING CONSOLE (WCP)	Cracked	275.00 F	*275.00 F
						F=Franchise part.
					Sub Total (S\$)	6,105.00 6,030.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	610.50 603.00
					Total Parts (S\$)	6,715.50 6,633.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	120.00	30.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,320.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >