

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	12:01HRS	BUS REGISTRATION NUMBER	SMB8030X
ACCIDENT DATE	27-Mar-23	BUS TYPE (SD/DD)	SD
BUS CAPTAIN NAME	CHAN YAT MUN	BUS ROUTE NO.	
OWN DAMAGE CLAIM AGAINST	MSFCL	BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	GEARBOX	1 <i>cut</i>	\$ 78,203.56
2	HYDRO VIBRATION DAMPER	1 <i>mg</i>	\$ 12,455.18
3	COOLING WATER PIPE	1 <i>dis</i>	\$ 891.00
4	PROPELLER SHAFT ASSY	1 <i>lt</i>	\$ 9,166.70
		8% GST	\$ 8,057.32
		PARTS TOTAL COST	\$ 108,773.76

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- - ITEM NO. 1 - 4 - COMMISSION OF GEARBOX	3250 4550 \$ 6,500.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	8% GST \$ 520.00 LABOUR TOTAL COST \$ 7,020.00

SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

BUS TYPE (SD / DD)	SD
--------------------	----

7
5 days

DATE IN	27-Mar-2023
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	10

Acknowledged by Repairer

Signature:

Date:

Tanfulin 97495749 / 62563561
Not Authorize EX50K
Revert
27/3/23 @ 430pm
5 days
Tanfulin @ lkkauto.com

SUMMARY	
SECTION NO.	COST
1	\$ 108,773.76
2	\$ 7,020.00
3	-
4	-
TOTAL	\$ 115,793.76