

# ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	12:01HRS	BUS REGISTRATION NUMBER	SMB8030X
ACCIDENT DATE	27-Mar-23	BUS TYPE (SD/DD)	SD
BUS CAPTAIN NAME	CHAN YAT MUN	BUS ROUTE NO.	
OWN DAMAGE CLAIM AGAINST	MSFCL	BUS ADVERT (Y/N)	N

## SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	GEARBOX	1	\$ 78,203.56
2	HYDRO VIBRATION DAMPER	1	\$ 12,455.18
3	COOLING WATER PIPE	1	\$ 891.00
4	PROPELLER SHAFT ASSY	1	\$ 9,166.70
		8% GST	\$ 8,057.32
		<b>PARTS TOTAL COST</b>	<b>\$ 108,773.76</b>

## SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none"><li>ITEM NO. 1 - 4</li><li>COMMISSION OF GEARBOX</li></ul>	\$ 6,500.00
SPRAY PAINTING \$640 PER PANEL	8% GST \$ 520.00
LABOUR CHARGES \$650 PER DAY	<b>LABOUR TOTAL COST</b> \$ 7,020.00

## SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

## SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

DATE IN	27-Mar-2023
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	10
BUS TYPE (SD / DD)	SD

SUMMARY	
SECTION NO.	COST
1	\$ 108,773.76
2	\$ 7,020.00
3	-
4	-
<b>TOTAL</b>	<b>\$ 115,793.76</b>