



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNH 6577E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	FRT BUMPER BODY ASSY (SN)	TO REPAIR SEE LABOUR	1,501.20	-
1	FRONT FENDER ASSY., R (SN)	BENT	864.00	864.00
1	EXT, REAR VIEW MIRROR ASSY., R (SN)	SCRATCHED	367.20	367.20
1	BRACKET, FRONT BUMPER, R (SN)	NOT NECESSARY	15.30	-
			2,847.70	1,251.20
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REPLACE FRONT BUMPER, FRONT RIGHT FENDER AND RIGHT SIDE MIRROR. INCLUSIVE OF THE REPAIR OF FRT BUMPER BODY ASSY.		1,500.00	1,300.00
	SPRAY PAINT FRONT BUMPER, FRONT RIGHT FENDER AND RIGHT SIDE MIRROR.		1,500.00	1,300.00
	TO CONDUCT BODY CAVITY PRESERVATION.		60.00	60.00
	TO CONDUCT ECU RE PROGRAMMING AND CLEAR OF ANY FAULT CODES TO ENSURE PROPER FUNCTION.		600.00	600.00
			3,660.00	3,260.00
	<b>GRAND TOTAL</b>		<b>6,507.70</b>	<b>4,511.20</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,511.20</b>

Report Ref No. CS/FCI23003139/Rqy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.