

E-Auto

(A Division of Vantage Automotive Limited)

Business Registration No. 53399829L GST Registration No. M2-0000551-1

305 Alexandra Road
159942 Singapore
Tel : 6376 8833
Fax : 6477 7398

BYD

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BY 5768	Date Estimated 29/03/2023	Page No. 1 of 1
Prepared By Clement Chia Cher-Yang		

ESTIMATE REPAIR FOR Tan Seow Wee Blk 683B Jurong West Central 1 #12-106 Singapore 642683	ACCOUNT 14356 MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNH6577E	LC0CE4DC1N0371496	17/11/2022	e6 (ME-2)	8749

DESCRIPTION	VALUE
TO CONDUCT THIRD PARTY INSURANCE CLAIM AGAINST MS FIRST CAPITAL INS(SBS6316B). DOA:26.3.23	0.00
TO REMOVE AND REPLACE FRONT BUMPER,FRONT RIGHT FENDER AND RIGHT SIDE MIRROR	1300 1500.00
SPRAY PAINT FRONT BUMPER,FRONT RIGHT FENDER AND RIGHT SIDE MIRROR	1300 1500.00
TO CONDUCT BODY CAVITY PRESERVATION	60.00
TO CONDUCT ECU RE PROGRAMMING AND CLEAR OF ANY FAULT CODES TO ENSURE PROPER FUNCTION	600.00
SUNDRIES nec	20 100.00
Total Labour 1:	3,760.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
12718253-00	FRT BUMPER BODY ASSY repair	1	1,668.00	10.00	1,501.20
12204772-00	FRONT FENDER ASSY.,R	1	960.00	10.00	864.00
12747576-00	EXT.REAR VIEW MIRROR ASSY.,R	1	408.00	10.00	367.20
11816553-00	BRACKET,FRONT BUMPER,R	1	17.00	10.00	15.30
Total Parts :					2,747.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp

Date

Labour 1	S\$	3,760.00
Parts	S\$	2,747.70
Labour 2	S\$	0.00
Excess	S\$	0.00
Total GST @ 8%	S\$	520.62
Grand Total	S\$	7,028.32

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.