

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23003143/TQY3Q2**Date:** 23/05/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000479	
<b>Claimant Vehicle No :</b>	SHA2097H	<b>Insured Vehicle No :</b>	SMG2768P	
Date of Loss:	24/03/2023	Nature of Claim:	TP	Claim No: M2301945

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2097H	Engine No:	D4FDGU706201
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU098272
Reg. Date:	25/01/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,546.08	1,683.84	1,862.24	52.52
Miscellaneous Items	71.00	71.00	0.00	0.00
Labour	1,680.00	1,190.00	490.00	29.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,297.08</b>	<b>2,944.84</b>	<b>2,352.24</b>	<b>44.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>(S\$)</b>	5,297.08	2,350.00	2,947.08	55.64
<b>+ GST 8.00/8.00% (S\$)</b>	423.77	188.00	235.77	55.64
<b>Nett Amount (S\$)</b>	<b>5,720.85</b>	<b>2,538.00</b>	<b>3,182.85</b>	<b>55.64</b>

INSPECTION

Date of Assignment:	27/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/03/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2097H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	553.00 FL	*553.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
4	1		*RR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	160.60 FL	*- FL
5	1		*RR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	160.60 FL	*- FL
6	1		*REAR BUMPER BRACKET LH	Not Necessary	35.60 FL	*- FL
7	1		*REAR BUMPER BRACKET RH	Not Necessary	35.60 FL	*- FL
8	1		*REAR BUMPER UNDER COVER	Deformed	228.00 FL	*228.00 FL
9	1		*REAR BUMPER REFLECTOR LAMP LH	Cracked	32.00 FL	*32.00 FL
10	1		*REAR BUMPER REFLECTOR LAMP RH	Cracked	32.00 FL	*32.00 FL
11	1		*EXHAUST SILENCER LH	Not Necessary	967.70 FL	*- FL
12	1		*EXHAUST SILENCER RH	Not Necessary	967.70 FL	*- FL
13	1		*REAR END PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
14	1		*REAR PANEL	Bent	526.70 FL	*526.70 FL
15	1		*REAR BUMPER REVERSE SENSOR	Not Working	180.00 F	*180.00 F
					Sub Total (S\$)	
					4,387.60	2,059.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	
					841.52	375.96
					Total Parts (S\$)	
					3,546.08	1,683.84

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	TOWING FEE	60.00	60.00
2	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>71.00</b>	<b>71.00</b>

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	900.00	560.00
2	SPRAY PAINTING CHARGE	New	600.00	600.00
3	REMOVE/REFIX EXHAUST	New	120.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,680.00</b>	<b>1,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >