

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123003144/KWY3Q2**Date:** 24/04/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHF564M **Insured Vehicle No :** SMV3883D

Date of Loss: 23/03/2023 Nature of Claim: TP Claim No: CDMPG23000733

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF564M**

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR2H88200

Reg. Date: 29/01/2021 (Man. Year: 2020) Chassis No: JTDKB3FUX03093722

Colour: Metallic Pearl White/Red Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm Rear Left Side: Wanli 6 mm

Front Right Side: Sailun 9 mm Rear Right Side: Wanli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 13,007.25 | 4,352.88 | 8,654.37 | 66.53 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,100.00 | 1,540.00 | 3,560.00 | 69.80 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 18,107.25 | 5,892.88 | 12,214.37 | 67.46 |
| + GST 8.00/8.00% (S\$) | 1,448.58 | 471.43 | 977.15 | 67.46 |
| Nett Amount (S\$) | 19,555.83 | 6,364.31 | 13,191.52 | 67.46 |

INSPECTION

Date of Assignment: 27/03/2023

Date Inspected: 27/03/2023 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 19 Apr 2023) |
| Parts: | 144 | TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHF564M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *PANEL SUB-ASSY ,FRONT DOOR ,LH | Bent | 1,641.36 FL | *1,641.36 FL |
| 2 | 1 | | *FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE ,LH | Serviceable | 243.81 FL | *- FL |
| 3 | 1 | | *HANDLE ASSY ,FRONT DOOR OUTSIDE ,LH | Serviceable | 493.40 FL | *- FL |
| 4 | 1 | | *WEATHERSTRIP ,FRONT DOOR ,LH | Serviceable | 292.32 FL | *- FL |
| 5 | 1 | | *HINGE ASSY ,FRONT DOOR ,LOWER LH | Repair | 139.86 FL | *- FL |
| 6 | 1 | | *HINGE ASSY ,FRONT DOOR ,UPPER LH | Repair | 123.06 FL | *- FL |
| 7 | 1 | | *TAPE ,BLACK OUT ,NO.1 FRT LH | Necessary | 16.91 FL | *16.91 FL |
| 8 | 1 | | *TAPE ,BLACK OUT ,NO.2 FRT LH | Necessary | 55.02 FL | *55.02 FL |
| 9 | 1 | | *TAPE ,BLACK OUT ,NO.3 FRT LH | Necessary | 33.29 FL | *33.29 FL |
| 10 | 1 | | *MOTOR ASSY ,POWER WINDOW REGULATOR ,FRT LH | Serviceable | 1,161.83 FL | *- FL |
| 11 | 1 | | *REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,LH | Serviceable | 300.62 FL | *- FL |
| 12 | 1 | | *UNIT ASSY ,HEADLAMP ,LH | Serviceable | 3,325.56 FL | *- FL |
| 13 | 1 | | *ABSORBER ASSY ,SHOCK,FRONT LH | Serviceable | 596.19 FL | *- FL |
| 14 | 1 | | *ARM SUB-ASSY ,FRONT SUSPENSION ,LOWER NO.1 LH | Serviceable | 959.81 FL | *- FL |
| 15 | 1 | | *KNUCKLE STEERING ,LH | Bent | 836.64 FL | *836.64 FL |
| 16 | 1 | | *RIM | Serviceable | 1,995.11 FL | *- FL |
| 17 | 1 | | *HUB CAP | Dented | 222.08 FL | *222.08 FL |
| 18 | 1 | | *FENDER SUB-ASSY ,FRONT LH | Bent | 1,236.69 FL | *1,236.69 FL |
| 19 | 1 | | *BRACE SUB-ASSY ,FENDER APRON LH | Repair | 368.24 FL | *- FL |
| 20 | 1 | | *LINER ,FRONT FENDER LH | Cracked | 265.55 FL | *265.55 FL |
| 21 | 1 | | *EMBLEM ,SIDE PANEL | Necessary | 68.88 FL | *68.88 FL |
| 22 | 1 | | *COVER ,FRONT BUMPER | Bent | 659.40 FL | *659.40 FL |
| 23 | 1 | | *SUPPORT ,FRONT BUMPER SIDE ,LH | Distorted | 100.49 FL | *100.49 FL |
| 24 | 1 | | *STAY SUB-ASSY ,FRONT BUMPER ,LH | Serviceable | 59.85 FL | *- FL |
| 25 | 1 | | *BRACKET ,FRONT BUMPER SIDE ,LH | Serviceable | 74.97 FL | *- FL |
| 26 | 1 | | *MOULDING FRONT BUMPER SIDE ,LH | Cracked | 120.86 FL | *120.86 FL |
| 27 | 1 | | *MOULDING ASSY ,BODY ROCKER PANEL ,LH | Serviceable | 624.54 FL | *- FL |
| 28 | 1 | | *SET DOOR TRIM CLIP | Not Necessary | 70.00 FS | *- FS |
| 29 | 1 | | *SET DOOR WEATHERSTRIP CLIP | Not Necessary | 65.00 FS | *- FS |
| 30 | 1 | | *DOOR STICKER TRANS-CAB | Necessary | 100.00 FS | *60.00 FS |
| 31 | 1 | | *TYRE (\$250.00) (90%) | Cut | 350.00 FS | *225.00 FS |
| 32 | 1 | | *SET CLIP ,ROCKER PANEL MOULDING | Not Necessary | 65.00 FS | *- FS |
| 33 | 1 | | *SET BUMPER CLIP FRT | Necessary | 65.00 FS | *60.00 FS |
| 34 | 1 | | *SET FRONT BUMPER RETAINER CLIP | Not Necessary | 85.00 FS | *- FS |
| 35 | 1 | | *SET FENDER CLIP | Not Necessary | 130.00 FS | *- FS |
| 36 | 1 | | *FENDER LINER CLIP | Necessary | 65.00 FS | *65.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------|----------|
| Sub Total (S\$) | 17,011.34 | 5,667.17 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 4,004.09 | 1,314.29 |
| Total Parts (S\$) | 13,007.25 | 4,352.88 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS | New | 240.00 | 60.00 |
| 2 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 3 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME. | New | 1,600.00 | 500.00 |
| 4 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR | New | 380.00 | 0.00 |
| 5 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 1,600.00 | 880.00 |
| 6 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 0.00 |
| 7 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 20.00 |
| 8 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 9 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 60.00 |
| 10 | TO REMOVE AND REFIT OF REAR FENDER FITITNGS ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 5,100.00 | 1,540.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >