

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 4757C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEEP CUT	821.90	561.20
1	FRONT BUMPER SIDE RETAINER O/S	BENT	65.50	35.50
1	SET FRONT BUMPER CLIPS	NECESSARY	39.00	39.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	387.80	-
1	FRONT BUMPER FOG LAMP O/S	NOT NECESSARY	366.50	-
1	FRONT BUMPER FOG LAMP GARNISH O/S	NOT NECESSARY	381.90	-
1	HEADLAMP LED O/S	HOLDER CRACKED	1,815.20	1,322.30
1	HEADLAMP LOWER BRACKET O/S	NO SUCH PARTS	66.80	-
1	FRONT FENDER O/S	DENTED	455.20	421.30
1	FRONT FENDER INNER SHIELD O/S	NOT NECESSARY	166.20	-
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NOT NECESSARY	39.00	-
1	FRONT FENDER INNER ARCH PANEL O/S	TO REPAIR SEE LABOUR	291.30	-
	LESS 20% DISCOUNT		-	-475.86
			4,896.30	1,903.44
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM.	NOT NECESSARY	120.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER ARCH PANEL O/S.		600.00	300.00
	TO PUTTY & SPRAY PAINTING.		800.00	400.00
			1,740.00	750.00
	GRAND TOTAL		6,636.30	2,653.44



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI23003145/Uqy3e2

CHUA KANG SENG

Licensed Appraiser