

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23003146/AYA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001062324
Claimant Vehicle No :	SJE7122R	Insured Vehicle No :	SFJ38T
Date of Loss:	25/03/2023	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE7122R	Engine No:	R18A13034229
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16308S215634
Reg. Date:	06/05/2008 (Man. Year: 2008)	Odometer:	175425 km
Colour:	Red		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,990.56	3,219.84	1,770.72	35.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	1,860.00	2,900.00	60.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,750.56	5,079.84	4,670.72	47.90
Approved Total (Overridden) (\$\$)		4,050.00		
Nett Amount (\$\$)	9,750.56	4,050.00	5,700.56	58.46
+ Loss of Use (8.0 x \$S\$100.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		26.75		
Nett Liability (\$\$)		4,876.75		
Global Sum Settlement (\$\$)		4,800.00		

INSPECTION

Date of Assignment:	27/03/2023	
Date Inspected:	28/03/2023 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts: 143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJE7122R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	698.60 FL	*698.60 FL
2	2		*REAR BUMPER SIDE RETAINER	Damaged	78.80 FL	*78.80 FL
3	1		*REAR BUMPER EXHAUST GARNISH	Not Necessary	38.90 FL	*- FL
4	1		*REAR FENDER INNER TRIM	N/S Deformed	499.80 FL	*249.90 FL
5	2		*TAILLAMP	Cracked	599.20 FL	*599.20 FL
6	2		*TAILLAMP LOWER BRACKET	Not Necessary	58.20 FL	*- FL
7	1		*BOOTLID	Dented	695.70 FL	*695.70 FL
8	1		*BOOTLID NUMBER PLATE GARNISH	Not Necessary	128.30 FL	*- FL
9	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	130.40 FL	*- FL
10	2		*BOOTLID REFLECTOR	Not Necessary	399.60 FL	*- FL
11	1		*BOOTLID INSULATOR	Not Necessary	187.60 FL	*- FL
12	4		*BOOTLID INNER STOPPER	Not Necessary	72.00 FL	*- FL
13	2		*BOOTLID HINGE	Not Necessary	96.00 FL	*- FL
14	1		*BOOTLID TOP LOCK	Damaged	194.90 FL	*194.90 FL
15	1		*BOOTLID LOWER LOCK	Not Necessary	15.00 FL	*- FL
16	1		*BOOTLID LOGO	Necessary	39.40 FL	*39.40 FL
17	1		*BOOTLID EMBLEM 1.8	Necessary	17.00 FL	*17.00 FL
18	1		*BOOTLID EMBLEM V-TECH	Necessary	37.10 FL	*37.10 FL
19	1		*BOOTLID EMBLEM CIVIC	Necessary	29.10 FL	*29.10 FL
20	1		*BOOTLID WEATHER STRIP	Cut	154.00 FL	*154.00 FL
21	1		*REAR END PANEL	Dented	387.30 FL	*387.30 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	127.80 FL	*127.80 FL
23	1		*REAR FLOOR PANEL TOP BOARD	Deformed	316.00 FL	*316.00 FL
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*REAR BUMPER EXHAUST GARNISH CLIP	Not Necessary	30.00 FS	*- FS
27	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS
28	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET BOOTLID NUMBER PLATE LAMP COVER GARNISH CLIP	Not Necessary	20.00 FS	*- FS
30	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
32	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
33	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
34	1		*REAR EXHAUST CHROME PIPE (SPECAIL TYPE)	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,990.70	3,944.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,000.14	724.96
Total Parts (\$)	4,990.56	3,219.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	280.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TRANFER BOOTLID MECHANISM	New	80.00	60.00
9	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,760.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >