

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003181/UYA3Q2**Date:** 31/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220003916		
Claimant Vehicle No :	GBG3674A	Insured Vehicle No :	YQ89J		
Date of Loss:	27/03/2023	Nature of Claim:	TP	Claim No:	5987327046SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3674A	Engine No:	1KD2669839
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	KDY2318028406
Reg. Date:	26/07/2017 (Man. Year: 2016)	Odometer:	137816 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Sailwin 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Sailwin 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,818.90	6,341.47	17,477.43	73.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	1,830.00	3,090.00	62.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,738.90	8,171.47	20,567.43	71.57
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	28,738.90	6,500.00	22,238.90	77.38
+ GST 8.00/8.00% (S\$)	2,299.11	520.00	1,779.11	77.38
Nett Amount (S\$)	31,038.01	7,020.00	24,018.01	77.38
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,522.00		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment:	28/03/2023		Fastech Auto Pte Ltd (HQ)
Date Inspected:	28/03/2023	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Estimated Period of Repair:	5.0 days		Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	672.10 F	*661.20 FL
2	1		*FRONT BUMPER BRACKET O/S	Not Necessary	233.50 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
4	1		*FRONT PANEL	Not Necessary	1,566.10 F	*- FL
5	1		*FRONT WINDSCREEN RUBBER	Cut	433.10 F	*288.10 FL
6	1		*FRONT CORNER PANEL TOP GARNISH O/S	Not Necessary	328.90 F	*- FL
7	1		*FRONT CORNER PANEL BLACK GARNISH O/S	Not Necessary	141.50 F	*- FL
8	1		*FRONT CORNER PANEL GARNISH O/S	Not Necessary	485.10 F	*- FL
9	1		*HEADLAMP O/S	Cracked	1,866.10 F	*1,021.10 FL
10	1		*HEADLAMP LOWER RUBBER O/S	Not Necessary	32.00 F	*- FL
11	1		*FRONT DOOR O/S	Badly Dented	1,960.10 F	*1,794.20 FL
12	1		*FRONT DOOR OUTER HANDLE O/S	Not Necessary	422.50 F	*- FL
13	1		*FRONT DOOR INNER LOCK O/S	Damaged / Malfunction	366.50 F	*305.10 FL
14	1		*FRONT DOOR INNER TRIM O/S	Deformed / Torn	715.10 F	*566.50 FL
15	1		*SET FRONT DOOR INNER TRIM CLIPS O/S	Necessary	30.00 F	*30.00 FL
16	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Scratched	166.20 F	*166.20 FL
17	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Jammed	485.20 F	*322.10 FL
18	1		*FRONT DOOR HINGES	Lower Bent	264.60 F	*105.20 FL
19	1		*FRONT DOOR MIRROR O/S	Broken	161.00 F	*161.00 FL
20	1		*FRONT DOOR INNER RUBBER LOWER O/S	Necessary	86.10 F	*86.10 FL
21	1		*FRONT DOOR INNER RUBBER O/S	Necessary	229.10 F	*182.50 FL
22	1		*FRONT DOOR SIGNAL LAMP O/S	Broken	182.50 F	*142.30 FL
23	1		*FRONT DOOR OUTER PILLAR O/S	Repair	981.20 F	*- FL
24	1		*FRONT DOOR INNER LOCK ACTUATOR O/S	No such part	415.10 F	*- FL
25	1		*FRONT DOOR INNER CHANNEL RUBBER O/S	Twisted	335.10 F	*299.10 FL
26	1		*FRONT STEP PANEL O/S	Repair	305.20 F	*- FL
27	1		*FRONT STEP PANEL GARNISH O/S	Cut	366.30 F	*318.30 FL
28	1		*FRONT WHEEL ARCH PANEL O/S	Repair	545.10 F	*- FL
29	1		*FRONT WHEEL ARCH PANEL GARNISH O/S	Not Necessary	112.00 F	*- FL
30	1		*FRONT WHEEL ARCH INNER PANEL O/S	Repair	325.50 F	*- FL
31	1		*FRONT SHOCK ABSORBER O/S	Bent / Twisted	292.50 F	*266.10 FL
32	1		*FRONT LOWER ARM O/S	Not Necessary	962.30 F	*- FL
33	1		*FRONT TOP ARM O/S	Not Necessary	662.50 F	*- FL
34	1		*FRONT KNUCKLE ARM O/S	Bent / Damaged	855.10 F	*855.10 FL
35	1		*FRONT TIE ROD END O/S	Not Necessary	228.50 F	*- FL
36	1		*FRONT STEERING RACK ASSY	Not Necessary	2,655.00 F	*- FL
37	1		*FRONT STEEL RIM O/S	Repair	100.00 F	*- FL
38	1		*FRONT MUDFLAP P/S	Grazed	325.10 F	*325.10 FL
39	1		*DROP SIDEGATE O/S	Repair	2,655.10 F	*- FL
40	1		*SET DROP SIDEGATE CORPORATE STICKER O/S	Necessary	500.00 FS	*200.00 FS
41	1		*SET FRONT DOOR CORPORATE STICKER O/S	Necessary	280.00 FS	*150.00 FS
42	1		*FRONT DOOR ROC STICKER O/S	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,818.90	8,325.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,983.83
Total Parts (\$\$)	23,818.90	6,341.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	180.00	40.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
5	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	380.00	150.00
6	TO DIAGNOSTIC & REPROGRAMME SYSTEM	New	180.00	0.00
7	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
8	TO DISMANTLE & REFIX FRINT DASHBOARD	New	380.00	0.00
9	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	80.00	60.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	1,800.00	700.00
Gross Labour Cost (S\$)			4,920.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >