

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23003184/AVY3Q2**Date:** 27/06/2023**REFERENCE**

Insured/Claimant: AMINAH BEEVVEE D/O SHAHUL HAMID
Date of Loss: 22/03/2023

Policy No: SP2001983579-01
Nature of Claim: OD

Claim No: 202332006502

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND4988L**
Make & Model: VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A) Engine No: CAV168293
Reg. Date: 17/06/2010 (Man. Year: 2010) Chassis No: WVGZZZ1TZA078944
Colour: Bronze Odometer: 144409 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$20,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Alventi 6 mm Rear Left Side: Alventi 6 mm
Front Right Side: Alventi 6 mm Rear Right Side: Alventi 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,342.36	17,099.39	9,242.97	35.09
Miscellaneous Items	3,122.00	1,822.00	1,300.00	41.64
Labour	6,280.00	4,030.00	2,250.00	35.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,744.36	22,951.39	12,792.97	35.79
Approved Total (Overridden) (S\$)		14,000.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	35,744.36	12,000.00	23,744.36	66.43
+ GST 8.00/8.00% (S\$)	2,859.55	960.00	1,899.55	66.43
Nett Amount (S\$)	38,603.91	12,960.00	25,643.91	66.43

INSPECTION

Date of Assignment: 28/03/2023 Present Location: Chia Auto Services Pte Ltd (HQ)
23 KAKI BUKIT AVENUE 4
Date Inspected: 28/03/2023 Inspected At: #02-03A AAS KAKI BUKIT CENTRE
SINGAPORE 415933
Repairer: Chia Auto Services Pte Ltd (HQ)
Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 1.4 TSI CL 5T13NZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND4988L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER GARNISH	Cracked	280.00 F	*280.00 F
2	1		*FRONT WINDSCREEN MOULDING	Not Necessary	90.00 F	*- F
3	1		*BONNET	Distorted	520.00 F	*520.00 F
4	2		*BONNET HINGE	Bent	100.00 F	*100.00 F
5	1		*BONNET ABSORBER	Not Necessary	155.30 F	*- F
6	1		*BONNET LOCK	Damaged	90.00 F	*90.00 F
7	1		*FRONT BUMPER	Distorted	460.00 F	*460.00 F
8	1		*FRONT BUMPER LOWER LIP	Distorted	280.00 F	*280.00 F
9	1		*FRONT BUMPER SIDE RETAINER	N/S Damaged	74.00 F	*37.00 F
10	1		*FRONT BUMPER REINFORCEMENT	Bent	230.00 F	*230.00 F
11	1		*FRONT BUMPER SPONGE	Cracked	80.00 F	*80.00 F
12	2		*FRONT BUMPER FOG LIGHT	Cracked	266.40 F	*266.40 F
13	2		*FRONT BUMPER FOG LIGHT COVER	Cracked	180.00 F	*180.00 F
14	1		*FRONT BUMPER CORNER PROTECTOR	N/S Missing	140.00 F	*70.00 F
15	1		*FRONT BUMPER CORNER PROTECTOR CHROME	N/S Missing	110.00 F	*55.00 F
16	1		*FRONT BUMPER TOWING HOOD	Deformed	41.00 F	*41.00 F
17	1		*FRONT BUMPER UNDER COVER GARNISH	Torn	211.00 F	*211.00 F
18	1		*FRONT BUMPER LOWER CENTER GRILLE	Deformed	140.00 F	*140.00 F
19	1		*FRONT BUMPER UPPER GRILLE	Missing	310.00 F	*310.00 F
20	1		*FRONT BUMPER UPPER GRILLE CHROME	Cracked	188.00 F	*188.00 F
21	1		*FRONT BUMPER UPPER GRILLE LOGO	Necessary	69.00 F	*69.00 F
22	1		*FRONT FENDER	Distorted	576.60 F	*288.30 F
23	2		*FRONT FENDER INNER COWLING (N/S)	Torn	288.00 F	*288.00 F
24	2		*FRONT FENDER INNER GUARD	Not Necessary	140.00 F	*- F
25	1		*WHEEL HOUSE PANEL	Distorted	953.60 F	*476.80 F
26	2		*HEADLAMP	Cracked	1,078.00 F	*1,078.00 F
27	1		*FRONT SUPPORT PANEL	Distorted	511.40 F	*511.40 F
28	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	155.30 F	*155.30 F
29	2		*FRONT KNUCKLE ARM	Damaged	642.00 F	*642.00 F
30	2		*FRONT LOWER ARM	Bent	510.00 F	*510.00 F
31	2		*FRONT KNUCKLE ARM BEARING	Damaged	380.00 F	*380.00 F
32	2		*FRONT STABILIZER BAR LINKAGE	Bent	180.00 F	*180.00 F
33	2		*FRONT SHOCK ABSORBER	Bent	532.00 F	*532.00 F
34	1		*FRONT DRIVESHAFT	N/S Damaged	2,467.00 F	*1,233.50 F
35	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,855.40 F	*- F
36	1		*CROSSMEMBER	Damaged	2,355.60 F	*2,355.60 F
37	1		*RADIATOR	Cracked	420.00 F	*420.00 F
38	2		*RADIATOR FAN MOTOR WITH BLADE	Not Necessary	645.00 F	*- F
39	1		*RADIATOR FAN COWLING	Not Necessary	105.00 F	*- F
40	1		*RADIATOR TOP COVER GARNISH	Not Necessary	82.00 F	*- F
41	1		*AIRCON CONDENSOR	Cracked	455.30 F	*455.30 F
42	1		*AIRCON SUCTION PIPE	Not Necessary	211.50 F	*- F
43	1		*AIRCON PRESSURE PIPE	Not Necessary	190.00 F	*- F
44	2		*HORN	Not Necessary	170.00 F	*- F
45	1		*INTER COOLER	Not Necessary	433.20 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	2		*COOLER AIR GUARD	Not Necessary	194.40 F	*- F
47	1		*AIR DUCT (FRONT)	Deformed	90.00 F	*90.00 F
48	1		*FRONT DOOR LH	Repair	655.30 F	*- F
49	1		*ROCKER PANEL	Buckled	480.00 F	*480.00 F
50	1		*REAR FENDER LH	Repair	820.30 F	*- F
51	2		*REAR KNUCKLE ARM WITH BEARING	Damaged	560.00 F	*560.00 F
52	2		*REAR SHOCK ABSORBER	Bent	440.00 F	*440.00 F
53	2		*REAR LOWER ARM	Bent	420.00 F	*420.00 F
54	1		*TAIL LAMP LH (OUTER)	Cracked	286.00 F	*286.00 F
55	1		*REAR BUMPER	Repair	520.00 F	*- F
56	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	50.00 F	*- F
57	1		*TOWING FEE	-	80.00 F	*- F
58	1		*BONNET LOCK CATCH	Not Necessary	-	*- F
59	1		*BONNET INSULATOR	Crumpled	-	*155.30 F
F=Franchise part.						
Sub Total (S\$)					23,947.60	15,544.90
+ Margin on L,N Items 10.00/10.00% (S\$)					2,394.76	1,554.49
Total Parts (S\$)					26,342.36	17,099.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	150.00	150.00
2	1	FRONT BONNET INSULATION CLIPS (SET) (NECESSARY)	20.00	20.00
3	1	FRONT BUMPER CLIPS (SET) (NECESSARY)	20.00	20.00
4	1	FRONT FENDER INNER COWLING CLIPS (SET) (NECESSARY)	20.00	20.00
5	1	FRONT NUMBER PLATE (DAMAGED)	50.00	50.00
6	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS (NECESSARY)	20.00	20.00
7	1	FRONT UNDERCOVER CLIPS (SET) (NECESSARY)	22.00	22.00
8	1	FRONT WINDSCREEN SEALANT (NOT NECESSARY)	100.00	0.00
9	1	FRONT WIPER GARNISH CLIPS (SET) (NECESSARY)	20.00	20.00
10	1	REAR BUMPER CLIPS (SET) (NOT NECESSARY)	20.00	0.00
11	1	WHEEL RIM (DAMAGED)	1,400.00	1,000.00
12	4	WHEEL TYRE (CUT)	1,280.00	500.00
Sub Total (\$\$)			3,122.00	1,822.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,400.00	1,800.00
2	TO SPRAY PAINT ON AFFECTED AREA	New	2,000.00	1,600.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECKTUFF COAT	New	140.00	30.00
5	TO REMOVE AND REFIX AIRCON CONDENSOR AND TOP UP GAS	New	120.00	60.00
6	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	60.00
7	TO REMOVE AND REFIX ENGINE	New	550.00	0.00
8	TO REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
9	TO REMOVE AND REFIX FRONT AND REAR UNDERCARRIAGE	New	400.00	300.00
10	TO REMOVE AND REFIX FRONT DOOR MECHANISM	New	100.00	0.00
11	FOUR WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (S\$)			6,280.00	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >