

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123003188/WWP3E2**Date:** 27/04/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00185982202

**Claimant Vehicle
No :** SGJ23Z**Insured Vehicle
No :** SDV3218G

Date of Loss: 11/03/2023

Nature of Claim: TP

Claim
No: SNM23D201947/C02/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGJ23Z**

Make & Model: TOYOTA CAMRY, 2.5 G HYBRID CVT (A)

Engine No: A25A0072257

Reg. Date: 06/03/2018 (Man. Year: 2017)

Chassis No: AXVH701012544

Colour: Silver

Odometer: 62108 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,497.57	5,648.78	3,848.79	40.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,440.00	2,220.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,157.57	7,088.78	6,068.79	46.12
Approved Total (Overridden) (\$\$)		5,650.00		
Nett Amount (\$\$)	13,157.57	5,650.00	7,507.57	57.06

INSPECTION

Date of Assignment: 28/03/2023

Date Inspected: 28/03/2023

Inspected At: Jementah Motor Works (HQ)
14 Defu Lane 10, #01-406
Singapore 539195

Estimated Period of Repair: 3.0 days

Adjuster: Mohdakid**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2023)
Parts:	143	TOYOTA CAMRY 2.5 G HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ23Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP - LH	Cut	3,616.84 FL	*2,778.00 FL
2	1		*FRONT BUMPER	Scratched	895.80 FL	*574.24 FL
3	1		*FRONT BUMPER LOWER MOULDING	Not Necessary	110.85 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP	Not Necessary	348.45 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Scratched	398.30 FL	*398.30 FL
6	1		*FRONT BUMPER SIDE RETAINER - LH	Broken	80.15 FL	*55.60 FL
7	1		*FRONT BUMPER PDC SENSOR	Not Necessary	295.00 FL	*- FL
8	1		*FRONT FENDER - LH	Dented	795.90 FL	*561.65 FL
9	1		*FRONT FENDER INNER SHIELD	Not Necessary	140.60 FL	*- FL
10	1		*FRONT FENDER HYBRID EMBLEM	Necessary	85.49 FL	*50.00 FL
11	1		*FRONT WHEEL RIM - LH	Scratched	984.60 FL	*650.00 FL
12	1		*FRONT WHEEL HUB }	Necessary	227.01 FL	*339.57 FL
13	1		*FRONT WHEEL BEARING }		186.50 FL	*- FL
14	1		*FRONT SHOCK ABSORBER	Not Necessary	377.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM	Damaged	499.80 FL	*386.94 FL
16	1		*FRONT LOWER ARM	Damaged	445.61 FL	*288.12 FL
17	1		*FRONT DOOR - LH	Buckled	1,405.70 FL	*1,101.03 FL
18	1		*FRONT DOOR RUBBER	Necessary	230.50 FL	*174.93 FL
19	1		*FRONT DOOR SIDE MIRROR	Repair	846.00 FL	*- FL
20	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
21	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
22	1		*FRONT TYRE LH	Cut	400.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,490.10	7,488.38
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,992.53	1,839.60
Total Parts (\$\$)	9,497.57	5,648.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT SENSOR	New	150.00	30.00
3	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	300.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
5	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	60.00
6	TO APPLY UNDERCOATING	New	150.00	60.00
7	PANEL BEATING	New	1,400.00	600.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,660.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >