



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FZ 7608T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FORK T-UNDER BRACKET (CONSISTENT)	NOT NECESSARY	500.00	-
1	STEERING CONE (CONSISTENT)	NECESSARY	300.00	220.00
1	SET FRONT DISC BRAKE (CONSISTENT)	NOT NECESSARY	800.00	-
1	FRONT FENDER (CONSISTENT)	CRACKED	280.00	196.00
1	HEAD LAMP (CONSISTENT)	DENTED	350.00	350.00
1	HEAD LAMP STAY (CONSISTENT)	BENT	250.00	120.00
1	HEAD LAMP BRACKET RIGHT (CONSISTENT)	BENT	200.00	58.00
1	HEAD LAMP BRACKET LEFT (CONSISTENT)	BENT	200.00	58.00
1	HEAD COVER (CONSISTENT)	CUT	120.00	120.00
1	FRONT SIGNAL LIGHT RIGHT (CONSISTENT)	CRACKED	150.00	85.00
1	FRONT SIGNAL LIGHT LEFT (CONSISTENT)	CRACKED	150.00	85.00
1	METER (CONSISTENT)	BROKEN	950.00	950.00
1	HANDLE BAR (CONSISTENT)	BENT	300.00	214.00
1	HANDLE BALANCER (CONSISTENT)	CUT	100.00	80.00
1	CLUTH LEVER (CONSISTENT)	CUT	120.00	58.00
1	BRAKE LEVER (CONSISTENT)	BENT	120.00	65.00
1	SET MIRROR (CONSISTENT)	MISSING (1PIECE ONLY)	180.00	95.00
1	CLUTH HOLDER (CONSISTENT)	BROKEN	120.00	62.40
1	CLUTH CABEL (CONSISTENT)	BROKEN	100.00	55.00
1	HORN SWITCH (CONSISTENT)	NOT NECESSARY	180.00	-
1	CRASH BAR N/S (CONSISTENT)	CUT	450.00	155.00
1	REAR FAIRING COVER N/S (CONSISTENT)	CUT	300.00	300.00
1	REAR FOOTREST LEFT (CONSISTENT)	BENT	120.00	120.00
1	REAR FOOTREST BRACKET LEFT (CONSISTENT)	BENT	220.00	220.00
1	FRONT FOOTREST LEFT (CONSISTENT)	BENT	150.00	80.00
1	FRONT FOOTREST BRACKET LEFT (CONSISTENT)	BENT	280.00	160.00
1	REAR SIGNAL LIGHT LEFT (CONSISTENT)	NOT NECESSARY	150.00	-
1	REAR BOX (CONSISTENT)	NOT FITTED	650.00	-
	LESS 10% DISCOUNT		-779.00	-390.64
			7,011.00	3,515.76

Report Ref No. CS/HSB23003196/Wvp3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FORK (SN) (CONSISTENT)	BENT	1,200.00	50.00
1	FRONT SPORT RIM (SN) (CONSISTENT)	SCRATCHED	950.00	50.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	30.00	10.00
1	HANDLE BRACKET (SN) (CONSISTENT)	BENT	280.00	50.00
1	PHONE HOLDER (SN) (CONSISTENT)	MISSING	80.00	30.00
1	FUEL TANK (SN) (CONSISTENT)	DENTED	850.00	80.00
1	REAR SWING ARM (SN) (CONSISTENT)	DAMAGED	1,200.00	100.00
	LESS 10% DISCOUNT		-459.00	-
			4,131.00	370.00
	<u>LABOUR</u>			
	SPRAY COVERSET.		500.00	350.00
	LABOUR.		800.00	450.00
			1,300.00	800.00
GRAND TOTAL			12,442.00	4,685.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CS/HSB23003196/Wvp3m4

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.