



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 6041U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	881.70	-
10	FRONT BUMPER CLIP	NOT NECESSARY	35.00	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	27.50	-
1	LH FRONT FENDER	BENT	580.00	580.00
1	LH FRONT FENDER UNDERSHIELD	SERVICEABLE	155.00	-
10	LH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	35.00	-
1	LHF FENDER WORDING "HYBRID"	NECESSARY	68.70	68.70
1	LH FRONT FENDER PROTECTOR	DENTED / DISTORTED	195.00	195.00
10	LH FRONT FENDER PROTECTOR CLIP	NECESSARY	35.00	35.00
1	LH FRONT RIM	DENTED	801.00	801.00
	LESS 20% DISCOUNT		-562.78	-335.94
			2,251.12	1,343.76
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, FRT BUMPER LOWER GARNISH, LHF FENDER, LHF DOOR). INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		800.00	350.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, FRT BUMPER LOWER GARNISH, LHF FENDER, LHF DOOR).		1,000.00	680.00
	TO CHECK WIRING. (NPA)	NOT NECESSARY	-	-
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO TUFF COAT.		100.00	30.00
			2,020.00	1,120.00
	GRAND TOTAL		4,271.12	2,463.76

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00
---	--	--	-----------------

Report Ref No. CS/SMR23003199/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.