

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003202/UWP3Q2**Date:** 24/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00047162300		
Claimant Vehicle No :	FBQ2164J	Insured Vehicle No :	SNE3019K		
Date of Loss:	22/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202198/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ2164J	Engine No:	G3E6E0510085
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0153263
Reg. Date:	19/08/2019 (Man. Year: 2019)	Odometer:	113023 km
Colour:	Green		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	110-70-17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,967.50	4,070.80	2,896.70	41.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	300.00	580.00	65.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,847.50	4,370.80	3,476.70	44.30
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	7,847.50	3,500.00	4,347.50	55.40

INSPECTION

Date of Assignment:	29/03/2023		
Date Inspected:	29/03/2023	Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ2164J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Not Necessary	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
3	1		*HANDLE -BAR	Bent	168.00 FL	*145.00 FL
4	1		*HANDLE -BAR END	Cut	95.00 FL	*30.00 FL
5	1		*HAND GRIP	Cut	68.00 FL	*68.00 FL
6	1		*MASTER PUMP	Damaged / Jammed	455.00 FL	*300.00 FL
7	1		*N/S SIDE MIRROR	Cut	128.00 FL	*60.00 FL
8	1		*CLUTCH LEVER	Cut	88.00 FL	*55.00 FL
9	1		*N/S FRONT SIGNAL	Cut	160.00 FL	*90.00 FL
10	1		*HORN INNER PANEL	Cut	150.00 FL	*150.00 FL
11	1		*FRONT INNER COVER	Cut	190.00 FL	*145.00 FL
12	1		*SET FAIRING ASSY	Cut	680.00 FL	*550.00 FL
13	1		*FRONT FOOTREST BRACKET	Not Necessary	186.00 FL	*- FL
14	2		*FRONT FOOTREST	Bent	148.00 FL	*148.00 FL
15	1		*GEAR PEDAL	Bent	98.00 FL	*98.00 FL
16	1		*BRAKE PEDAL	Bent	185.00 FL	*125.00 FL
17	2		*REAR FOOTREST	Cut	150.00 FL	*150.00 FL
18	2		*REAR FOOTREST BRACKET	Cut	360.00 FL	*280.00 FL
19	1		*EXHAUST PROTECTOR -REAR	Cut	90.00 FL	*85.00 FL
20	1		*EXHAUST PROTECTOR -FRONT	No such part	85.00 FL	*- FL
21	1		*EXHAUST PIPE END COVER	Cut	75.00 FL	*60.00 FL
22	1		*ENGINE COVER	Cut	485.00 FL	*320.00 FL
23	1		*REAR SIGNAL (O/S)	Cracked	140.00 FL	*60.00 FL
24	1		*REAR RIM SHAFT	Cut	128.00 FL	*48.00 FL
25	1		*SWING ARM	Cut	580.00 FL	*480.00 FL
26	1		*SWING ARM BUSH	Not Necessary	185.00 FL	*- FL
27	1		*SWING ARM SHAFT	Not Necessary	118.00 FL	*- FL
28	1		*REAR EXHAUST	Damaged	485.00 FL	*485.00 FL
29	1		*SET NUMBER PLATE	Rear Bent	38.00 FS	*10.00 FS
30	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
31	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
32	1		*SET STEERING CONE	Not Necessary	90.00 FS	*- FS
33	1		*ENGINE OIL (50%)	Necessary	24.00 FS	*12.00 FS
34	1		*GASKET	Necessary	95.00 FS	*70.00 FS
35	1		*SET STICKER	Necessary	120.00 FS	*60.00 FS
36	1		*REAR BOX	Cut	480.00 FS	*380.00 FS
37	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,618.00	4,464.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	650.50	393.20
Total Parts (\$\$)	6,967.50	4,070.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	420.00	300.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
Gross Labour Cost (S\$)			880.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >