

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG23003203/WVY3M4**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220098989
Claimant Vehicle No :	GBL7620C	Insured Vehicle No :	SNH238Z
Date of Loss:	25/03/2023	Nature of Claim:	TP
		Claim No:	2237706254SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL7620C		
Make & Model:	NISSAN NV350 URVAN, 2.0 PANEL VAN 5MT (M)	Engine No:	QR20020948R
Reg. Date:	28/03/2022 (Man. Year: 2021)	Chassis No:	JN1MA2E26Z0000418
Colour:	Grey	Odometer:	11327 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	28/03/2023	
Date Inspected:	29/03/2023	Inspected At: Polymath Garage Pte Ltd - Kaki Bukit (HQ) 1 Kaki Bukit Avenue 6, #01-15 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: Mohdakid**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$65,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	0.00 F	*- F
2	1		*REAR END PANEL	Repair	0.00 F	*- F
3	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
4	1		*REAR O/S AIR VENT	Broken	0.00 F	*- F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*REAR O/S FENDER	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL	New	0.00	0.00
2	RESPRAY	New	0.00	0.00
Gross Labour Cost (S\$)			0.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >