



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 9791R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR MUDGUARD	DEFORMED	85.00	85.00
1	REAR NUMBER PLATE LIGHT	CRACKED	38.00	38.00
1	REAR MUDGUARD BRACKET	NOT NECESSARY	52.00	-
1	REAR BOX BRACKET	CRACKED	160.00	160.00
1	REAR GIVI BOX	SCRATCHED	230.00	230.00
1	REAR FORK	NOT NECESSARY	350.00	-
1	REAR SPORT RIM	TO REPAIR SEE LABOUR	380.00	-
1	REAR BRAKE DISK	SCRATCHED	110.00	110.00
1	EXHAUST PIPE COVER	SCRATCHED	65.00	65.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	480.00	-
1	RADIATOR COVER	DEFORMED	40.00	40.00
1	SET BODY	SCRATCHED	450.00	450.00
1	FRONT MUDGUARD	SCRATCHED	45.00	45.00
1	FRONT HEADLAMP	SCRATCHED	320.00	320.00
1	FRONT FORK	BENT	350.00	350.00
1	STEERING CONE STAND	BENT	180.00	180.00
1	STEERING CONE	NECESSARY	90.00	90.00
1	FRONT BRAKE DISK	SCRATCHED	110.00	110.00
1	FRONT ABS DISK	SCRATCHED	38.00	38.00
1	FRONT RIM SUB	BENT	25.00	25.00
1	HANDLE BALANCER	SCRATCHED	45.00	45.00
1	HANDLE GRIP	SCRATCHED	55.00	55.00
1	SET BRAKE LEVER	SCRATCHED	90.00	90.00
1	HANDLE BAR	NOT NECESSARY	60.00	-
1	MIRROR	BROKEN	45.00	45.00
1	HANDLE BAR COVER	NOT NECESSARY	65.00	-
1	FRONT WINDSCREEN	SCRATCHED	58.00	58.00
1	FRONT LAMP STAY	BENT	45.00	45.00
1	CAMERA	SCRATCHED	480.00	480.00

Report Ref No. CS/LIP23003209/Rny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BRAKE CALIPER	NOT NECESSARY	220.00	-
1	FRONT FOOTREST PLATE	SCRATCHED	90.00	90.00
1	ABS MOTOR	NOT WORKING	1,450.00	1,450.00
	LESS 10% DISCOUNT		-630.10	-469.40
			5,670.90	4,224.60
	<u>LABOUR</u>			
	TOWING.		40.00	40.00
	JACK & ALIGNMENT FRT&RR BODY.		650.00	500.00
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR SPORT RIM AND EXHAUST PIPE.		600.00	400.00
			1,290.00	940.00
GRAND TOTAL			6,960.90	5,164.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS/LIP23003209/Rny3e2

MARKET VALUE: \$13,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$5,689.00=NETT VALUE: \$7,311.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.