



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1642E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE	WARPED	900.00	900.00
1	REAR FENDER LH	DEFORMED	450.00	450.00
1	REAR LAMP LH	CRACKED	147.00	147.00
1	TAIL GATE BRACKET	BENT	98.00	98.00
1	SET FLOOR BOARD	NOT NECESSARY	1,800.00	-
1	STICKER	NECESSARY	35.00	35.00
	LESS 15% DISCOUNT		-514.50	-244.50
			2,915.50	1,385.50
5	WOODEN BEAM @\$650.00 (SN)	CRACKED (4PCS ONLY)	3,250.00	1,800.00
2	CANOPY PILLAR @\$800.00 (SN)	BENT	1,600.00	900.00
2	WOODEN CANOPY @\$450.00 (SN)	SMASHED	900.00	500.00
	LESS 15% DISCOUNT		-862.50	-
			4,887.50	3,200.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGE PARTS, PANEL BEAT WHERE NECESSARY.		2,000.00	1,200.00
	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION.		850.00	500.00
	TO CHECK WIRING FUNCTIONS.		120.00	30.00
			2,970.00	1,730.00
	GRAND TOTAL		10,773.00	6,315.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,050.00

Report Ref No. CS/SMO23003210/Any3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.