

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC23003214/Wvy3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	04/04/2023	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBF 2487K	Veh. Inspected	k	SMQ 3499G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/027176	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		28/03/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO 1.6 EX	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF3416MK5051940	Colour		BLUE	
	Odometer	49900 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	KUMHO		5 mm	
	L/H Front Tyre	205/55 R16	KUMHO		5 mm	
	R/H Rear Tyre	205/55 R16	KUMHO		7 mm	
	L/H Rear Tyre	205/55 R16	KUMHO		7 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	24/03/2023	Inspect Date /	Time	28/03/2023 ( 02:56 PM )	
	Survey held at	YAP LEE MOTOR				
		BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883				
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23003214/Wvy3e2

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser