

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23003260/AQP3E2**Date:** 04/07/2023**REFERENCE**

Insured/Claimant:	Ethan Yi-Peng Koh	Policy No:	2100477030	
Date of Loss:	07/03/2023	Nature of Claim:	OD	Claim No: 7670133391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE585K	Engine No:	CZC546610
Make & Model:	AUDI A3 SPORTBACK, 1.4 TFSI (A)	Chassis No:	WAUZZZ8V2GA148296
Reg. Date:	27/07/2016 (Man. Year: 2016)	Odometer:	75893 km
Colour:	Bronze		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,807.00	4,579.68	9,227.32	66.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,332.00	2,072.00	6,260.00	75.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,139.00	6,651.68	15,487.32	69.95
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,539.00	6,051.68	15,487.32	71.90
+ GST 8.00/8.00% (S\$)	1,723.12	484.13	1,238.99	71.90
Nett Amount (S\$)	23,262.12	6,535.81	16,726.31	71.90

INSPECTION

Date of Assignment:	29/03/2023		
Date Inspected:	28/03/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	2,328.00 FS	*1,862.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	213.00 FS	*- FS
3	2		*REAR BUMPER LOCKING MECHANISM - LH / RH	Not Necessary	34.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	279.00 FS	*- FS
5	1		*REAR BUMPER SIDE REINFORCEMENT	Dented	680.00 FS	*543.60 FS
6	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	32.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	79.00 FS	*- FS
8	1		*REAR PARKING AID SENSOR - INNER / OUTER (2PCS)	Damaged (1Pc Only)	543.00 FS	*212.00 FS
9	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
10	1		*SET REAR BUMPER WIRING	Not Necessary	578.00 FS	*- FS
11	1		*REAR OUTER TAIL LIGHT - RH	Cut	1,030.00 FS	*824.00 FS
12	1		*REAR INNER TAIL LIGHT - RH	Cracked	1,030.00 FS	*824.00 FS
13	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	49.00 FS	*- FS
14	1		*REAR LID	Repair	3,373.00 FS	*- FS
15	1		*PACKING ADHESIVE	Necessary	22.00 FS	*16.88 FS
16	1		*REAR LID ATTACHMENT PARTS	Not Necessary	326.00 FS	*- FS
17	1		*REAR LID FLAP GASKET	Not Necessary	242.00 FS	*- FS
18	1		*REAR LID LOCK	Not Necessary	196.00 FS	*- FS
19	1		*REAR LID FLAP LOCK COVER CAP	Not Necessary	9.00 FS	*- FS
20	1		*REAR LID LOCK STRIKER	Not Necessary	104.00 FS	*- FS
21	2		*REAR LID STOP BUFFER - LH / RH	Not Necessary	55.00 FS	*- FS
22	1		*AUDI EMBLEM	Necessary	152.00 FS	*121.60 FS
23	1		*A3 INSCRIPTION	Necessary	110.00 FS	*87.60 FS
24	1		*TFSI INSCRIPTION	Necessary	110.00 FS	*87.60 FS
25	1		*REAR SPOILER FIXING PARTS	Not Necessary	194.00 FS	*- FS
26	1		*REAR SPOILER FOAM STRIPS	Not Necessary	162.00 FS	*- FS
27	1		*REAR WINDOW	Not Necessary	961.00 FS	*- FS
28	1		*WINDOW PRIMER	Not Necessary	24.00 FS	*- FS
29	1		*REAR WHEEL HOUSING LINER	Not Necessary	281.00 FS	*- FS
30	1		*RAER WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
31	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **13,807.00** **4,579.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	0.00
3	TO RENEW REAR WINDSCREEN	New	480.00	0.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
7	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND RHS REAR FENDER	New	3,500.00	1,100.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			8,332.00	2,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >