

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23003261/UPA3Q2**Date:** 14/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900022362
<b>Claimant Vehicle No :</b>	SJU1233J	<b>Insured Vehicle No :</b>	SMJ3420U
Date of Loss:	27/03/2023	Nature of Claim:	TP
		Claim No:	7554167487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJU1233J</b>	Engine No:	HR15005411B
Make & Model:	NISSAN LATIO, 1.5 Sports (A)	Chassis No:	JN1FAAC11Z0010108
Reg. Date:	18/11/2009 (Man. Year: 2008)	Odometer:	270054 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Rotalla 6 mm	Rear Left Side:	Rotalla 6 mm
Front Right Side:	Rotalla 6 mm	Rear Right Side:	Rotalla 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,639.23	6,001.17	3,638.06	37.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	2,590.00	1,950.00	42.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,179.23</b>	<b>8,591.17</b>	<b>5,588.06</b>	<b>39.41</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>14,179.23</b>	<b>6,800.00</b>	<b>7,379.23</b>	<b>52.04</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		26.75		
<b>Nett Liability (\$\$)</b>		<b>7,426.75</b>		

INSPECTION

Date of Assignment:	29/03/2023		
Date Inspected:	29/03/2023	Inspected At:	Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390 Singapore 408700
Estimated Period of Repair:	7.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	1,484.60 FN	*1,314.70 FN
2	2		*TAIL GATE DAMPERS	Not Necessary	614.40 FN	*- FN
3	1		*TAIL GATE TRIM COVER	Deformed / Cracked	280.00 FN	*280.00 FN
4	1		*TAIL GATE EMBLEM	Necessary	70.00 FN	*45.00 FN
5	1		*TAIL GATE PLATE NISMO	Necessary	100.00 FN	*50.00 FN
6	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	120.00 FN	*86.40 FN
7	1		*SET TAIL GATE WINDSCREEN TAPE FROM	Necessary	54.00 FS	*40.00 FS
8	1		*TAIL GATE WINDSCREEN INNER SEALANT	Necessary	126.00 FS	*40.00 FS
9	1		*TAIL GATE TOP LOCK	Bent	138.50 FN	*138.50 FN
10	1		*TAIL GATE LOWER LOCK	Not Necessary	40.00 FN	*- FN
11	1		*TAIL GATE CENTRE HOLDER	Cracked	213.00 FN	*213.00 FN
12	2		*TAIL LAMPS	Cracked	710.20 FN	*710.20 FN
13	1		*TAIL GATE RUBBER	Twisted	181.40 FN	*145.80 FN
14	2		*TAIL LAMP INNER PANEL	Repair	561.80 FN	*- FN
15	1		*REAR PANEL	Badly Dented	516.50 FN	*485.00 FN
16	1		*REAR PANEL GARNISH	Twisted	97.80 FN	*97.80 FN
17	2		*REAR FENDERS TRIM COVER	Deformed / Cracked	1,034.60 FN	*672.20 FN
18	1		*REAR BUMPER	Distorted	702.70 FN	*645.10 FN
19	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	180.00 FS	*180.00 FS
20	2		*REAR BUMPER SIDE HOLDERS	Necessary	96.40 FN	*96.40 FN
21	1		*SET REAR BUMPER INNER CLIPS	Necessary	45.00 FS	*30.00 FS
22	10		*REAR BUMPER LOWER SPOILER CLIPS	No such part	50.00 FN	*- FN
23	1		*REAR BUMPER INNER SPONGE	Torn	59.20 FN	*59.20 FN
24	2		*REAR NUMBER PLATE LAMPS	Not Necessary	173.40 FN	*- FN
25	1		*REAR BUMPER LOWER SPOILER	Cracked / Torn	1,012.20 FN	*800.00 FN
26	1		*REAR BUMPER SIDE BRACKETS	Not Necessary	96.00 FN	*- FN
27	1		*REAR SPARE TYRE TOP COVER	Warped	390.00 FN	*390.00 FN
28	1		*REAR PANEL LOWER CENTRE COVER	Cracked	72.00 FN	*72.00 FN
29	1		*REAR WINDSCREEN SUN X STICKER	Not Necessary	205.00 FS	*- FS
30	1		*REAR WINDSCREEN WIPER MOTOR	Not Necessary	817.80 FS	*- FS
31	1		*REAR CENTRE LOCK SWITCH	Not Necessary	178.20 FS	*- FS
32	1		*REAR NUMBER PLATE WITH COVER	Bent	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,520.70</b>	<b>6,631.30</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	881.47	630.13
<b>Total Parts (\$\$)</b>	<b>9,639.23</b>	<b>6,001.17</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUSTPROOF	New	150.00	60.00
2	TO DISMANTLE /RENEW TAIL GATE	New	150.00	60.00
3	TO REMOVE /REFIT REAR TOP SPOILER	New	100.00	0.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO DISMANTLE /RENEW REVERSE SENSORS	New	100.00	50.00
6	TO REMOVE/REFIT REAR INTERIOR TO EFFECT REPAIR	New	100.00	80.00
7	TO DISMANTLE /RENEW REAR BUMPER SPOILER	New	150.00	0.00
8	TO REMOVE/REFIT REAR WINDSCREEN	New	140.00	120.00
9	TO DISMANTLE /RENEW ACCIDENT PORTION	New	1,800.00	1,100.00
10	TO SPRAY PAINT	New	1,800.00	1,100.00
<b>Gross Labour Cost (S\$)</b>			<b>4,540.00</b>	<b>2,590.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >